



## CHEROKEE NATION Environmental Programs

---

# LEAD-BASED PAINT INSPECTION & RISK ASSESSMENT REPORT

**Conducted At:**

Address: 16 S. Ora St  
City State Zip: Pryor, OK 74361  
Coordinates: 36.30450, 95.30650  
Built in: 1947

**Prepared For:**

HACN Housing Rehabilitation - George Hubbard  
Using ODEQ, EPA and CN Work Practice Standards  
Established in 40 CFR 745-227

**Inspected By:**

*Samuel Tyler Moore*

---

Samuel Tyler Moore  
**OKRASR804155942, CNRASR00042**

Cherokee Nation Environmental Programs  
PO Box 948, Tahlequah, OK 74465  
(918) 453-5000  
Oklahoma Firm: OKFIRM11198  
Cherokee Nation Firm: CNFIRM00001

Report Date: April 7, 2025

## CONTENTS

<b>1.0 EXECUTIVE SUMMARY .....</b>	<b>3</b>
<b>2.0 DISCLOSURE.....</b>	<b>4</b>
<b>3.0 INSPECTION/ RISK ASSESSMENT METHODOLOGY.....</b>	<b>4</b>
3.1 Surface-by-Surface Inspection Methodology.....	4
3.2 X-Ray Fluorescence Analyzer Lead Detector.....	4
3.3 Risk Assessment Methodology .....	5
3.4 Description of Paint Condition Hazard Rankings.....	5
3.5 Laboratory Analysis .....	5
<b>4.0 DESCRIPTION OF RESULTS .....</b>	<b>5</b>
4.1 LBP Inspection .....	6
4.2 LBP Risk Assessment.....	6
4.3 Resident Questionnaire Form 5.0 .....	7
4.4 Building Condition Form 5.1.....	8
4.5 Dust Wipe Sample Analysis .....	8
4.6 Soil Sample ANALYSIS .....	9
<b>5.0 RECOMMENDATIONS.....</b>	<b>10</b>
5.1 Deteriorated Lead-Based Paint.....	10
5.2 Lead Dust Control Options .....	10
5.3 Lead in Soil .....	11
<b>6.0 Re-evaluation and Monitoring Schedule.....</b>	<b>11</b>
<b>APPENDIX A: XRF Field Data Sheets &amp; Floor Plan .....</b>	<b>12</b>
<b>APPENDIX B: Dust Wipe &amp; Soil Analysis.....</b>	<b>13</b>
<b>APPENDIX C: Scope of Work/Request.....</b>	<b>14</b>

## 1.0 EXECUTIVE SUMMARY

A lead-based paint inspection was conducted at the Kevin Mereo site on March 26, 2025, as requested by the Cherokee Nation Housing Rehabilitation Department. The inspection **confirmed the presence of lead** in amounts greater than or equal to 1.0 mg/cm<sup>2</sup> in paint, using the inspection protocol in Chapter 7 of the U.S. Department of Housing and Urban Development's (HUD) Guidelines for the Evaluation of Control of Lead-Based Paint Hazards in Housing (2012). A Risk Assessment was performed to fulfill the requirements for a federally assisted rehabilitation.

The full inspection report can be found in Appendix A (XRF Field Data Sheets). Building components that were unable to be tested with an XRF and are assumed positive include the following:

**The following is a summary of the survey findings for the subject property:**

### Interior Lead-Based Paint

Living Room	Window	Sill	Wood	A
Living Room	Window	Casing	Wood	A

### Exterior Lead-Based Paint

Exterior	Door	Outer Casing	Wood	A
Exterior	Window	Casing	Wood	A

### Deteriorated Lead-Based Paint (Lead-Based Paint Hazards)

- Living Room Window Sill Wood A
- Living Room Window Casing Wood A

### Lead in Dust Hazards

- Living Room Floor
- Living Room Windowsill
- Bathroom Floor
- Bed 1 Windowsill
- Bed 2 Floor
- Garage Floor

### Lead in Soil Hazards

- Results are below the hazard level

*This executive summary has been prepared for the convenience of the users of this report. This summary does not contain all the information presented in this report and, therefore, the entire report should be read to assure all pertinent information is transmitted.*

## 2.0 DISCLOSURE

A copy of this report or a summary of this report must be provided to new lessees (tenants) and purchasers of the property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers, and it must be made available to new tenants. Property owners (leasers) and sellers are also required to distribute an educational pamphlet approved by the US Environmental Protection Agency (EPA) and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

## 3.0 INSPECTION/ RISK ASSESSMENT METHODOLOGY

### 3.1 SURFACE-BY-SURFACE INSPECTION METHODOLOGY

A surface-by-surface lead-based paint inspection was performed to identify interior and exterior building components finished with lead-based paint. The inspection was performed inside the residence and on exterior surfaces of the residence using a portable X-Ray Fluorescence Analyzer (XRF). The inspection was limited to accessible painted and/or varnished surfaces. All substrates within inaccessible rooms are assumed positive for lead-based paint until access is available to prove otherwise.

The inspection was conducted in accordance with the EPA's work practice standards for conducting lead-based paint activities (40 CFR 745.227), HUD's Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (Guidelines) with the 2012 revisions. Samples were collected to represent component types; therefore, it should be assumed that similar component types in the rest of that room or room equivalent also contain lead-based paint. When standing in any four-sided room facing side A, which coincides with the front of the dwelling, side B will be to the right, side C will be to the rear, and side D will be to the left (clockwise from side A).

When evaluating this report it is assumed that, according to Chapter 7 HUD Guidelines, if one testing combination (i.e. window, door) is positive for lead in an interior or exterior room equivalent, all other similar testing combinations in those areas are assumed to be positive. The same is true for negative readings.

### 3.2 X-RAY FLUORESCENCE ANALYZER LEAD DETECTOR

The sampling strategy utilized to determine the presence of lead-based paint adheres to the EPA Performance Characteristic Sheet for the particular XRF instrument used, as well as the manufacturers' modifications and recommendations. The Heuresis PB200i lead x-ray fluorescence analyzer (Serial Number: 3177) was used for detection of building components finished with lead-based paint. The

instrument was manufactured by Viken Detection, 21 North Avenue, Burlington, MA 01803. The radioactive source is cobalt-57 and was last resourced on May 25, 2024.

Samples may be classified as positive or negative. Positive results indicate lead in quantities greater than 1.0 mg/cm<sup>2</sup> and are considered lead-based paint. Negative results indicate lead in quantities less than 1.0 mg/cm<sup>2</sup> and are not considered lead-based paint.

### 3.3 RISK ASSESSMENT METHODOLOGY

The lead-based paint risk assessment was performed to determine if the lead-based paint present in the residence presents an immediate hazard. This was accomplished through combining measurements of lead in dust, surface-by-surface paint analysis, visual assessment of the residence, assessment of paint condition, and by collecting maintenance and management data to identify and address lead-based paint hazards.

The risk assessment was performed in accordance with the EPA's work practice standards for conducting lead-based paint activities (40 CFR 745.227), HUD's Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (Guidelines) with the 2012 revisions.

### 3.4 DESCRIPTION OF PAINT CONDITION HAZARD RANKINGS

The paint condition is placed into one of two categories using the risk assessor's professional judgment. These categories are intact or deteriorated. Type of deterioration may also be noted on surfaces in deteriorated condition. Based on the approximate surface area of deteriorated paint, the risk assessor then assesses the paint condition as intact or deteriorated. These conditions indicate the potential for lead hazards associated with paint condition and lead in household dust.

Hazard ranking protocol was performed in accordance with the HUD Guidelines for Evaluation and Control of Lead-Based Paint Hazards in Housing, dated July 2012, Chapter 5: Risk Assessment and Reevaluation; Identification of Deteriorated Paint (Form 5.2). This information is summarized below.

#### ***Deteriorated***

*EPA regulations define deteriorated paint as "any interior or exterior paint or other coating that is peeling, chipping, chalking, or cracking, or any paint or coating located on an interior or exterior surface or fixture that is otherwise damaged or separated from the substrate" (40 CFR 745.63).*

### 3.5 LABORATORY ANALYSIS

Laboratory analysis of dust wipe/soil samples were performed by QuanTem Laboratories (NLLAP 101352), 2033 Heritage Park Drive, Oklahoma City, OK 73120 Phone: 405-755-7272. Laboratory analysis of the dust wipes and soil samples are analyzed based on the EPA SW846-7420/ HUD – Flame Atomic Absorption.

## 4.0 DESCRIPTION OF RESULTS

This is a report of an X-ray Fluorescence (XRF) inspection and risk assessment to determine if lead-based paint exists in the readily accessible areas of this residence and tested components. The presence or absence of lead-based paint only applies to surfaces tested or assessed on the date of the field visit.

According to HUD/EPA Guidelines, paint with concentrations of lead that exceed 1.0 mg/cm<sup>2</sup> must be considered a lead-based paint (LBP). However, detectable lead in quantities less than 1.0 mg/cm<sup>2</sup> may contribute to the development of lead dust hazards even though it is not considered a lead-based paint hazard.

#### 4.1 LBP INSPECTION

Lead based paint was found on both the interior and exterior of the site. The positive readings are shown in the following table. The full report with all readings is in Appendix 1.

#	Pb	Units	Pb Error Result	Secs	Date	Time	Room	Cho	Structure	Member	Substrate	Wall	Condition
13	3.2 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	15:47:15	Living	Roo	Window	Sill	Wood	A	Deteriorated
19	2.2 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	15:55:25	Living	Roo	Window	Sill	Wood	A	Deteriorated
21	2 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	15:56:44	Living	Roo	Window	Casing	Wood	A	Deteriorated
24	1.9 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	15:58:08	Living	Roo	Window	Casing	Wood	A	Deteriorated
36	2.9 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	16:10:48	Exterior	Door	Outer Casi	Wood	A	Deteriorated	
37	2.8 mg/cm <sup>2</sup>		0.3 Positive	2	3/26/2025	16:11:32	Exterior	Window	Casing	Wood	A	Deteriorated	

#### 4.2 LBP RISK ASSESSMENT

Lead-based paint hazards and dust hazards were identified during the survey.

**The lead hazards are:**

##### Interior Lead-Based Paint

Living Room	Window	Sill	Wood	A
Living Room	Window	Casing	Wood	A

##### Exterior Lead-Based Paint

Exterior	Door	Outer Casing	Wood	A
Exterior	Window	Casing	Wood	A
Exterior	Door	Outer Casing	Wood	A

**Lead in Dust Hazards:**

- Living Room Floor
- Living Room Windowsill
- Bathroom Floor
- Bed 1 Windowsill
- Bed 2 Floor
- Garage Floor

**Lead in Soil Hazards:**

- No

#### 4.3 RESIDENT QUESTIONNAIRE FORM 5.0

A resident questionnaire was completed as part of the Assessment, to help the identify particular use patterns, which may be associated with potential LBP hazards, such as opening and closing windows painted with LBP. The answers to the questionnaire were obtained during an interview with the occupants. Following is a summary of the information obtained during the interview.

Children in the Household:	0
Children's bed locations:	NA
Children's eating locations:	NA
Primary interior play area(s):	NA
Primary exterior play area(s):	NA
Pets:	None
Blood lead testing history:	-
Observed chewed surfaces:	-
Women of child bearing age:	0
Previous lead testing:	None
Frequently used entrances:	Front Door and Garage Door
Frequently opened windows:	None
Structure Cooling Method:	Window Units
Gardening –type and location:	None
Plans for landscaping:	None
Cleaning regimen:	Monthly
Cleaning Methods:	NA
Recent completed renovations:	Many ongoing projects including drywall, exterior wall and roof
Demolition debris on site:	None
Resident with work lead exposure:	None
Planned Renovations:	A scope of work document for this residence is included in Appendix C.

#### 4.4 BUILDING CONDITION FORM 5.1

Condition	Yes	No	Comments
Roof is missing parts of surfaces (tiles, boards, shales, etc.)	X		
Roof has holes or large cracks	X		
Gutters or downspouts broken, missing.	X		
Chimney masonry cracked, bricks loose or missing, obviously out of plumb.		X	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine painting.	X		
Exterior siding has missing boards or shingles	X		
Water stains on interior walls or ceilings	X		
Walls or ceilings deteriorated	X		
More than "very small*" amount of paint in a room deteriorated	X		
Two or more windows or doors broken, missing, or boarded up	X		
Porch or steps have major elements broken, missing, or boarded up.	X		
Foundation has major cracks, missing material, structure leans, or visibly unsound	X		
Total Number	11	1	

\*The "very small" amount is the de minimis amount under the HUD Lead Safe Housing Rule (24 CFR 35.1350(d)), or the amount of paint that is not "paint in poor condition" under the EPA lead training and certification ("402") rule (40 CFR 745.223)

Notes (including other conditions of concern):

#### 4.5 DUST WIPE SAMPLE ANALYSIS

Dust wipe samples were collected in an effort to help determine the levels of lead-containing dust on the interior windowsills and floors. The following tables note the presence or absence of lead hazards in dust per the EPA risk assessment and clearance standards. Please refer to Appendix B for detailed analytical reports. The presence of these hazards indicates that sample results exceed the following EPA criteria:

- **10 ug/ft<sup>2</sup> for floors, including carpeted floors**
- **100 ug/ft<sup>2</sup> for interior window sills**
- **100 ug/ft<sup>2</sup> for interior window troughs**
- **800 ug/ft<sup>2</sup> for exterior concrete**

The following table indicates the sample number, location, surface type, lead concentration, and presence or absence of lead dust hazards for dust wipe samples collected during this LBP Risk Assessment:

<b>Dust Wipe Sample Analysis</b>				
<b>Sample #</b>	<b>Location</b>	<b>Surface Types</b>	<b>Concentration (Micrograms/ft<sup>2</sup>)</b>	<b>Lead Hazard</b>
01	Living Room	Floor	31	Yes
02	Living Room	Windowsill	520	Yes
03	Bed 1	Floor	7.6	No
04	Bath	Floor	46	Yes
05	Bed 1	Windowsill	710	Yes
06	Bath	Windowsill	49	No
07	Bed 2	Floor	38	Yes
08	Garage	Floor (concrete)	96	Yes
09	Exterior Side A Porch	Floor (concrete)	48	No
10	Exterior Side A	Windowsill	81	No

#### 4.6 SOIL SAMPLE ANALYSIS

The EPA has established lead hazard standards for lead in soil under TSCA Section 403 (Residential Lead Hazards). Please refer to Appendix B for detailed analytical reports. The following level of lead in soil should be considered hazardous and may result in excessive lead exposure and elevated blood lead levels:

- 400 milligrams per kilogram (mg/Kg) in children's play areas with bare residential soil (e.g., sandboxes, gardens)
- 1,200 mg/Kg (average) in bare soil for the remainder of the yard.

The following table indicates the sample number, location, surface type, lead concentration, and presence or absence of lead soil hazards for soil samples collected during this LBP Risk Assessment:

<b>Soil Sample Analysis</b>				
<b>Sample #</b>	<b>Location</b>	<b>Bare or Covered</b>	<b>Concentration (Micrograms/ft<sup>2</sup>)</b>	<b>Lead Hazard</b>
11	Dripline	Bare	110	No

## 5.0 RECOMMENDATIONS

### 5.1 DETERIORATED LEAD-BASED PAINT

<b>Room or Exterior Location</b>	<b>Component</b>	<b>Type of Hazard</b>	<b>Approximate Area or Length</b>	<b>Acceptable Hazard Control Options</b>	
				<b>Interim</b>	<b>Abatement</b>
Living Room and Exterior Side A	Windowsill and Casing	Chips and Dust		Wet scrape and repaint	Remove and Replace
Exterior Side A	Front Door Casing	Chips and Dust		Wet scrape and repaint	Remove and Replace

### 5.2 LEAD DUST CONTROL OPTIONS

<b>Room</b>	<b>Surface</b>	<b>Acceptable Hazard Control Method</b>
Living Room Bath Garage Bed 2 Bed 2 Kitchen	Floor	Hepa-Vac/Wet wipe/Hepa-Vac
Living Room Bed 1	Windowsill	Hepa-Vac/Wet wipe/Hepa-Vac

### 5.3 LEAD IN SOIL

Type Of Area	Location	Acceptable Hazard Control Options	
No Hazards in soil			

## 6.0 RE-EVALUATION AND MONITORING SCHEDULE

Each of these treatments will need to be reexamined periodically to make certain that they remain effective and to ensure that new lead-based paint hazards do not appear. The interim controls shown above are less expensive initially, but they may be more expensive in the end since they need to be reevaluated more frequently. The replacement and paint removal methods are more expensive initially, but do not require any reevaluation.

The owner should monitor the condition of the paint at least annually or if there is some indication, that paint might be failing. A professional reevaluation is also needed. The standard schedule for reevaluation the dwelling is shown above.

**Re-evaluation:** Standard Re-evaluation Schedule 3 contained in the HUD Guidelines applies to this property, since one of the rooms had a dust lead level greater than the standard. Therefore, the dwelling should be reevaluated in April 2026 (12 months from now). If no lead-based paint hazards are identified at that time, another reevaluation should be conducted in April 2027 (2 years later). If no lead-based paint hazards are identified at that time, no further reevaluations are needed. However, since lead-based paint may be present in the dwelling, the owner should monitor the condition of all painted surfaces at least annually or whenever other information indicates a potential problem.

## APPENDIX A: XRF Field Data Sheets & Floor Plan

Viken Detection  
Pb200i  
XRF Lead Paint Analyzer

3177

Pb200i-5.3.1

#	Pb	Units	Pb Error	Result	Secs	Date	Time	Room/Choice	Structure	Member	Substrate	Wall Condition
1	1.01	mg/cm <sup>2</sup>	0.07	20.17	3/26/2025	15:38:00	Calibration					
2	1	mg/cm <sup>2</sup>	0.07	20.18	3/26/2025	15:38:56	Calibration					
3	0.99	mg/cm <sup>2</sup>	0.07	20.16	3/26/2025	15:39:52	Calibration					
4	0.5	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:42:45	Living Room	Room	Wall	Drywall	A Deteriorated
5	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:43:04	Living Room	Room	Wall	Drywall	B Deteriorated
6	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:43:25	Living Room	Room	Wall	Drywall	C Deteriorated
7	0.4	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:43:49	Living Room	Room	Wall	Drywall	D Deteriorated
8	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:44:10	Living Room	Room	Ceiling	Drywall	Deteriorated
9	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:44:55	Living Room	Room	Baseboard	Wood	B Deteriorated
10	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:45:36	Living Room	Room	Floor	Wood	Deteriorated
11	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:45:59	Living Room	Door	---	Wood	A Deteriorated
12	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:46:15	Living Room	Door	Jamb	Wood	A Deteriorated
13	3.2	mg/cm <sup>2</sup>	0.3	Positive	2	3/26/2025	15:47:15	Living Room	Window	Sill	Wood	A Deteriorated
14	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:50:37	Bedroom 1	Room	Wall	Drywall	A Deteriorated
15	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:50:58	Bedroom 1	Room	Wall	Drywall	B Deteriorated
16	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:51:15	Bedroom 1	Room	Wall	Drywall	C Deteriorated
17	0.2	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:51:33	Bedroom 1	Room	Wall	Drywall	D Deteriorated
18	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:52:00	Bedroom 1	Room	Ceiling	Drywall	Deteriorated
19	2.2	mg/cm <sup>2</sup>	0.3	Positive	2	3/26/2025	15:55:25	Living Room	Window	Sill	Wood	A Deteriorated
20	0.2	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:56:25	Living Room	Window	Casing	Wood	A Deteriorated
21	2	mg/cm <sup>2</sup>	0.3	Positive	2	3/26/2025	15:56:44	Living Room	Window	Casing	Wood	A Deteriorated
22	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:57:47	Living Room	Window	Casing	Wood	A Deteriorated
23	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	15:57:58	Living Room	Window	Casing	Wood	A Deteriorated
24	1.9	mg/cm <sup>2</sup>	0.3	Positive	2	3/26/2025	15:58:08	Living Room	Window	Casing	Wood	A Deteriorated
25	0	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	16:00:58	Bathroom	Room	Wall	Drywall	A Deteriorated
26	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	16:01:13	Bathroom	Room	Wall	Drywall	B Deteriorated
27	0.1	mg/cm <sup>2</sup>	0.3	Negative	2	3/26/2025	16:01:28	Bathroom	Room	Wall	Drywall	C Deteriorated

28	0.1 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:02:11	Bathroom	Room	Ceiling	Drywall	Deteriorated
29	0.1 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:03:22	Laundry	Room	Wall	Drywall	A
30	0.2 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:03:47	Laundry	Room	Wall	Drywall	C
31	0.3 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:04:40	Laundry	Room	Wall	Drywall	D
32	0 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:05:27	Laundry	Room	Ceiling	Drywall	Deteriorated
33	0.2 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:09:30	Exterior	Room	Wall	Wood	A
34	0 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:10:07	Exterior	Door	---	Wood	A
35	0.1 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:10:24	Exterior	Door	Jamb	Wood	A
36	2.9 mg/cm <sup>2</sup>	0.3 Positive	2	3/26/2025 16:10:48	Exterior	Door	Outer Casir	Wood	A
37	2.8 mg/cm <sup>2</sup>	0.3 Positive	2	3/26/2025 16:11:32	Exterior	Window	Casing	Wood	A
38	0.2 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:11:54	Exterior	Window	Sill	Wood	A
39	0.2 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:12:42	Exterior	Room	Wall	Wood	B
40	0.1 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:13:16	Exterior	Window	Apron	Wood	B
41	0.2 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:14:03	Exterior	Room	Wall	Wood	C
42	0.1 mg/cm <sup>2</sup>	0.3 Negative	2	3/26/2025 16:15:30	Exterior	Room	Wall	Wood	D
43	0.9 mg/cm <sup>2</sup>	0.2 Negative	5	3/26/2025 16:17:50	Exterior	Soffit	Wood	Wood	B
44	1.01 mg/cm <sup>2</sup>	0.07	20.22	3/26/2025 16:19:30	Calibration				Deteriorated
45	0.99 mg/cm <sup>2</sup>	0.07	20.22	3/26/2025 16:20:25	Calibration				
46	1.1 mg/cm <sup>2</sup>	0.07	20.07	3/26/2025 16:21:18	Calibration				

## APPENDIX B: DUST WIPE & SOIL ANALYSIS



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

## Environmental Chemistry Analysis Report

**QuanTEM Set ID:** 377774      **Client:** Cherokee Nation Environmental Programs  
**Date Received:** 03/28/25      **Client Name:** Tyler Moore  
**Received By:** Charlie Johnson  
**Date Sampled:**  
**Time Sampled:**      **Acct. No.:** C162  
**Analyst:**  
**Date of Report:** 04/01/25      **Location:** Pryor, OK  
AIHA LAP, LLC: 101352      **Project No.:** NA

QuanTEM ID	Client ID	Matrix	Parameter	Results	Reporting Limits	Units	Date/Time Analyzed	Method
001	01	Wipe	Lead	31	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
002	02	Wipe	Lead	520	3.6	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
003	03	Wipe	Lead	7.6	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
004	04	Wipe	Lead	46	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
005	05	Wipe	Lead	710	7.6	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
006	06	Wipe	Lead	49	3.8	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
007	07	Wipe	Lead	38	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
008	08	Wipe	Lead	96	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
009	09	Wipe	Lead	48	2.5	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
010	10	Wipe	Lead	81	6	ug/sq. Ft.	04/01/25 14:51	NIOSH 7082
011	11	Soil	Lead	110	25	mg/kg	03/31/25 16:10	Soil EPA 7000B (1)

Note: Sample results have not been corrected for blank values.

This report applies only to the standards or procedures indicated and to the specific samples tested. It is not indicative of the qualities of apparently identical or similar products or procedures, nor does it represent an ongoing assurance program unless so noted. These reports are for the exclusive use of the client and are not to be reproduced without specific written permission. QuanTEM is not responsible for user-supplied data used in calculations. Customer provided data such as volumes, areas, etc., cannot be verified by QuanTEM Laboratories, LLC.

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Wipe materials must meet ASTM E1792 criteria. Method detection limits and resultant reporting limits may not be valid for non-ASTM E1792 wipe material.

Measurement uncertainty available upon request.

EPA Method 7000B (1) = EPA 600/R-93/200 Preparation Modified. EPA 7000B Analysis Modified

EPA Method 7082 (2) = EPA 600/R-93/200 Preparation Modified. EPA 7082 Analysis Modified



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

## Environmental Chemistry Analysis Report

**QuanTEM Set ID:** 377774  
**Date Received:** 03/28/25  
**Received By:** Charlie Johnson  
**Date Sampled:**  
**Time Sampled:**  
**Analyst:**  
**Date of Report:** 04/01/25

AIHA LAP, LLC: 101352

**Client:** Cherokee Nation Environmental Programs  
Tyler Moore  
**Acct. No.:** C162  
**Location:** Pryor, OK  
**Project No.:** NA

<b>QuanTEM</b>		<b>Matrix</b>	<b>Parameter</b>	<b>Results</b>	<b>Reporting Limits</b>	<b>Units</b>	<b>Date/Time Analyzed</b>	<b>Method</b>
<b>ID</b>	<b>Client ID</b>							

Authorized Signature: 

Eric Caves, Chemistry Technical Manager

Note: Sample results have not been corrected for blank values.

This report applies only to the standards or procedures indicated and to the specific samples tested. It is not indicative of the qualities of apparently identical or similar products or procedures, nor does it represent an ongoing assurance program unless so noted. These reports are for the exclusive use of the client and are not to be reproduced without specific written permission. QuanTEM is not responsible for user-supplied data used in calculations. Customer provided data such as volumes, areas, etc., cannot be verified by QuanTEM Laboratories, LLC.

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Wipe materials must meet ASTM E1792 criteria. Method detection limits and resultant reporting limits may not be valid for non-ASTM E1792 wipe material.

Measurement uncertainty available upon request.

EPA Method 7000B (1) = EPA 600/R-93/200 Preparation Modified. EPA 7000B Analysis Modified

EPA Method 7082 (2) = EPA 600/R-93/200 Preparation Modified. EPA 7082 Analysis Modified

# Supplemental Report

## QAQC Results

**QA ID:** 21586  
**Test:** Lead

**Date:** 3/31/2025  
**Matrix:** Soil

**Lab Number:** 377774  
**Approved By:** Eric Caves  
**Date Approved:** 3/31/2025

**Notes:**

### Blank Data:

Type of Blank	Blank Value
FCB	0
ICB	0

### Standards Data:

Standard	Low Limit	Obtained	High Limit
FCV	2.2	2.57	2.8
CCV	2.2	2.47	2.8
RLVS	0.05	0.14	0.15
ICV	0.9	0.97	1.1

### Duplicate Data:

Sample Number	Result	Duplicate	% RPD
377780-004	0.000	0.000	#Num!

### Recovery Data:

Sample Number	Result	Spike Level	Result + Spike	% Recovery	Dup. Result + Spike	% Dup. Recovery	% Spike RPD
377780-004	0.000	2.000	2.090	104.5			
LCS-S	0.000	2.428	2.490	102.6	2.503	103.1	0.5

Authorized Signature: 

Eric Caves, Chemistry Technical Manager

# Supplemental Report

## QAQC Results

QA ID: 21590  
Test: Lead

Date: 4/1/2025  
Matrix: Wipe

Lab Number: 377774  
Approved By: Eric Caves  
Date Approved: 4/1/2025

Notes:

### Blank Data:

Type of Blank	Blank Value
FCB	0
ICB	0

### Standards Data:

Standard	Low Limit	Obtained	High Limit
FCV	2.2	2.57	2.8
CCV	2.2	2.57	2.8
RLVS	0.05	0.12	0.15
ICV	0.9	1.02	1.1

### Duplicate Data:

### Recovery Data:

Sample Number	Result	Spike Level	Result + Spike	% Recovery	Dup. Result + Spike	% Dup. Recovery	% Spike RPD
MS-W	0.000	2.428	2.635	108.5	2.597	107.0	1.5

Authorized Signature:






## LEAD CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502  
(800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

www.QuantTEM.com

## LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Contact Information		Project Information		Report Results ( <input checked="" type="checkbox"/> one box)	
Company: Cherokee Nation Environmental Programs	Phone: (918) 453-5000	Project Location: Pryor, OK	RECEIVED BY 	DATE & TIME 3/28/25 10:00 AM	QuantTEM Website <input checked="" type="radio"/> Email Tyler-Moore@cherokee.org <input type="radio"/> Other _____
Contact: Tyler Moore	Cell Phone: (918) 772-8709	Project ID: _____			
Account #: C 162	E-mail: Tyler-Moore@cherokee.org	PO Number: 895481			
SAMPLED BY: Name: Tyler Moore & Logan Girty	Date: 03/26/2025	VIA FedEx	RECEIVED BY 	DATE & TIME 3/28/25 10:00 AM	
RElinquished BY 					
DATE & TIME 3/25/2025 5 PM					
REQUESTED SERVICES (Please <input checked="" type="checkbox"/> the appropriate Boxes)					
No. (10 Characters Max)	Sample ID (10 Characters Max)	Sample Description	Volume or Area		
			Paint Chips <input type="radio"/> wt% <input checked="" type="radio"/> ppm <input type="radio"/> mg/cm <sup>2</sup>	Soil <input type="radio"/> mg/kg <input checked="" type="radio"/> ppm <input type="radio"/> wt%	Air (µg/m <sup>3</sup> ) <input type="radio"/> Wipes (µg/ft <sup>2</sup> ) <input type="radio"/> Bulk (mg/kg)
1	01	Living Room Floor	144 sq in	✓	
2	02	Living Room Windowsill	99 sq in	✓	
3	03	Bed 1 Floor	144 sq in	✓	
4	04	Bath Floor	144 sq in	✓	
5	05	Bed 1 Windowsill	47.5 sq in	✓	
6	06	Bath Windowsill	94.5 sq in	✓	
7	07	Bed 2 Floor	144 sq in	✓	
8	08	Garage Floor (concrete)	144 sq in	✓	
9	09	Side A Porch	144 sq in	✓	
10	10	Exterior Side A Windowsill	60 sq in	✓	
11	11	Drip Line Soil		✓	

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"  
Please Note - UPS and USPS are NOT available for Saturday Delivery