Will Rogers Downs Chiller Compressor #2 Replacement

Repair will take place after Jan 1, 2020. Compressor #2 is still in operation with no current issues but had a vibration test to be showing critical. Exact installation date will be determined after bid review. Compressor # 1 was replaced in spring of 2018.

Bid Breakdown

- Material Cost
- Labor Cost
- Crane Cost
- Availability of Compressor
- Time Frame of Repair (start to finish)
- Warranty

•

Bid Information

Daikin Chiller

Model # AWS300ADPEWNN-ER10 Serial # STNU110200021

Compressor #2

Model # HSA232QS17YA Serial # C-103246 Style # 332525262 Motor Style # 332121467

Crane Distance

Street to Compressor – 100 feet to crane location (Estimated). Vendor will need to confirm distance once bid awarded.

Space

5 feet between chiller and hydronic piping.

MVP 20807







