

**CHEROKEE NATION**  
**Environmental Programs**



**Asbestos Sampling Report**

**PARTICIPANT:** #13674

**PREPARED BY:** Tim Miller **DATE:** 9/2/2025  
**TIMOTHY MILLER, ENVIRONMENTAL SPECIALIST I**

**REQUESTED BY:** HACN HOUSING REHABILITATION –  
JAMIE WALTERS

## I. Site Inspection/Description

Cherokee Nation Environmental Programs (CNEP) has conducted asbestos sampling for the presence of asbestos containing materials (ACM) for the following site:

506 Mulberry Ave. Afton, OK 74331  
918-314-7024  
Coordinates: 36.68798, -94.95593

The sampling was performed to determine the presence of all ACM from within the affected parts of the structure for EPA's National Emissions of Hazardous Air Pollutants (NESHAP) compliance as well as OSHA worker protection.

The inspector responsible for this project was:

Timothy Miller, AHERA Inspector

The sampling was conducted on August 20, 2025 at the request of the Cherokee Nation Housing Rehabilitation Department.

The site is a single family home built in 1949. Sampling was limited to areas that would be affected by the project scope of work (Appendix A) provided by the housing rehabilitation department.

**ACM was found at this site.** See Section IV for locations.

## II. BACKGROUND

The Oklahoma Department of Environmental Quality (ODEQ) has adopted EPA's NESHAP regulation under OAC252:100, 41-15 and has been delegated authority in the state of Oklahoma for its enforcement. Section 61.145(a) of Federal EPA regulation states that prior to commencement of the demolition or renovation of a facility a thorough inspection of the affected part or parts of a facility is required to determine the presence of all asbestos including Category I and Category II non-friable, and friable ACM. ACM is defined by EPA and OSHA as any material that contains greater than 1% asbestos.

## III. FIELD PROCEDURES AND ANALYTICAL METHODS

During the on-site inspection, we visually assessed the physical characteristics of suspect asbestos-containing materials (SACM) based on homogeneous areas. Homogeneous areas are areas of asbestos similar in color, texture, and construction, date of application, and in general

appearance. For purposes of renovation and demolition, homogeneous areas of SACM can be further classified according to NESHAPs rules by whether the material is friable, Category I non-friable, or Category II non-friable.

Friable ACM is defined by NESHAPs rules as any material containing more than 1% asbestos as determined by Polarized Light Microscopy (PLM), that, when dry, can be crumbled, pulverized or reduced to powder by hand pressure.

Category I Non-friable ACM is defined by NESHAPs rules as any asbestos-containing packings, gaskets, construction mastics, resilient floor covering (i.e. floor tiles, roll sheet flooring) or asphalt roofing products that contain more than 1% asbestos as determined by PLM.

Category II Non-friable ACM is defined by NESHAPs rules as any material, excluding Category I non-friable ACM, containing more than 1% asbestos as determined by PLM, when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure.

Typically, non-friable materials, such as transite (cementitious products) and vinyl floor tiles are not regulated by the State of Oklahoma provided they do not become friable. General deterioration, machine grinding, drilling, sanding, and dry-buffing are all ways of causing non-friable materials to become classified as Regulated Asbestos Containing Materials (RACM). All friable materials are classified RACM. Please note that the following materials, even though classified as non-friable are fully regulated by Oklahoma Department of Labor for removal purposes as friable material: ceiling tiles, roll sheet flooring (linoleum), and joint wall compound when deemed friable

In addition to classification of suspect material into friable and non-friable materials, a determination of current condition was conducted as part of the physical assessment. The condition noted is the representative of the material at the time of inspection. Conditions of materials can change very quickly when disturbed. All suspect material was placed in one of the following categories of condition.

Significantly damaged: Material that is damaged, blistered, deteriorated, water stained over at least 10% of its total area.

Damaged: Material that is damaged, blistered, deteriorated, water stained less than 10% of its total area.

Good: Material that has no visible damage or deterioration.

Guidelines used for the number of samples collected per homogeneous area were determined using the Asbestos Hazard Emergency Response Act (AHERA) protocol promulgated in 40 CFR 763, Appendix E as follows:

Surfacing materials – material that is sprayed or troweled on wall, ceilings, or support columns for fireproofing, acoustical, or even decorative purpose.

- Less than 1000 ft<sup>2</sup> – Minimum 3 samples
- From 1000-5000 ft<sup>2</sup> – Minimum 5 samples
- Greater than 5000 ft<sup>2</sup> – Minimum 7 samples

Thermal System Insulation (TSI) materials – thermal system insulation material applied to tanks, boiler, pipes or other structural component for an insulating purpose.

- May omit areas of fibrous glass, foam glass, rubber, and Styrofoam from sampling. Areas that have mastic on seams or outer jacketing will be sampled.
- At least three samples must be collected from each homogeneous area of TSI.
- Plus an additional sample from each patched area of less than 6 linear feet.
- Fittings require a sufficient amount to determine positive or negative nature.
- Inspector will first collect samples from damaged areas, exposed ends, or areas missing jacketing first.

Miscellaneous materials – all other material that are not thermal system insulation or surfacing materials. This includes gaskets, packings, joint wall compound, cementitious asbestos materials, ceiling tiles resilient flooring materials, construction mastics, etc..

- May assume and document as such
- A sufficient amount of samples to determine negative or positive nature. A minimum or one per suspect homogeneous area.
- Collect samples from inconspicuous locations.
- Material such as cementitious asbestos or vibration dampening cloths should not be sampled and will be assumed ACM unless instructed by client to collect these samples.

Bulk samples of suspect ACM were analyzed by Polarized Light Microscopy (PLM) in accordance with EPA Methods 600R-93/116. All samples were sent to a NVLAP accredited laboratory for analysis. QuanTEM Laboratories, LLC (NVLAP # 101959-0) in Oklahoma City, OK analyzed the samples. A copy of the full laboratory report and chain of custody can be found in Appendix B.

#### IV. SUMMARY OF FINDINGS

---

A total of 74 samples were analyzed from 33 homogeneous areas due to multi-layers of material within some homogeneous sample areas. All accessible and observable areas within the renovation area were sampled for ACM. Samples were not taken of suspect materials that may have placed the inspector at risk of injury (i.e. electrical panel boxes). Any suspect ACM that have not been tested and/or found positive for asbestos must be assumed ACM until they are analyzed. Upon review of laboratory analysis, the following asbestos containing materials can be found in Table 1. All suspect ACM samples that were analyzed and did not contain asbestos can be found in Table 2.

Sample #	Material Description	Locations	Friability (Friable, NF Cat I, NF Cat II)	Condition	Sample Results (% Asbestos)
33-01	White Siding	Exterior Throughout	NF Cat II	Damaged	15

Sample #	Material Description	Locations	Condition	Sample Results (% Asbestos)
01-01 Through 01-03	Blue/White Wall & Ceiling Texture	Laundry Room	Damaged	None Detected
02-01	White Wall Patch	Laundry Room by Door	Damaged	None Detected
03-01	White Wall Patch	Laundry Room behind Washer	Damaged	None Detected
04-01	Brown Vinyl Tile	Office	Damaged	None Detected
05-01	White Vinyl Tile	Office	Damaged	None Detected
06-01 Through 06-03	Gray Wall Texture	Office	Damaged	<1
07-01 Through 07-03	Gray Ceiling Texture	Office	Damaged	None Detected
08-01 Through 08-03	Gray Wall Texture	Pantry/Office Walls	Damaged	None Detected
09-01	White Caulk	Office Baseboard	Good	None Detected
10-01	White Ceiling Tiles	Throughout	Damaged	None Detected
11-01	Tan Vinyl Tile	Bathroom 1	Damaged	None Detected
12-01	Clear Caulk	Bathroom 1 Baseboard	Damaged	None Detected
13-01	White Caulk	Bathroom 1 Baseboard	Damaged	None Detected
14-01	Yellow Formica	Bathroom 1	Good	None Detected
15-01 Through 15-03	Wall & Ceiling Texture	Bathroom 1	Damaged	None Detected
16-01	Camo Wallpaper	Kitchen	Damaged	None Detected
17-01	Countertop	Kitchen	Damaged	None Detected

18-01	Sink Cabinet Liner	Kitchen	Significantly Damaged	None Detected
19-01	Drywall	Kitchen, Below Sink	Significantly Damaged	None Detected
20-01	Pink Drywall	Bathroom 2	Damaged	None Detected
21-01	Mirror Tile	Bathroom 2	Damaged	None Detected
22-01	Clear Caulk	Bathroom 2	Damaged	None Detected
23-01 through 23-03	Ceiling Texture & Drywall	Bathroom 2	Damaged	None Detected
24-01	Gray Vinyl Tile	Bathroom 2	Damaged	None Detected
25-01	Brown Vinyl Tile	Bathroom 2	Damaged	None Detected
26-01	Joint Compound	HVAC Closet	Good	None Detected
27-01	White Caulk	HVAC Plenum	Good	None Detected
28-01	Tan Joint Compound	Bedroom 1 Wall	Good	None Detected
29-01	Tan Joint Compound	Bedroom 1 Window Sill	Damaged	None Detected
30-01	Brown Caulk	Living Room Window	Good	None Detected
31-01	Blue Drywall/Joint Compound	Living Room	Good	None Detected
32-01	Gray Shingle	Roof	Damaged	None Detected

## V. CONCLUSIONS

Asbestos is not always an immediate hazard. Intact and undisturbed ACM does not pose a health risk. They may, however become a health hazard if they are damaged, disturbed, or deteriorate over time and release fibers into the air. There are no federal, state, or Tribal laws mandating asbestos removal. It is only when the material can no longer be maintained in good condition and/or airborne concentrations of asbestos are measured and found to be above a permissible exposure limit (PEL), or when the building is to be demolished or renovated, that removal may become necessary. Any renovation/demolition work which may impact these positive materials should be conducted in accordance with all applicable Federal, state, and local regulations.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuanTEM Lab No. 382275

Client: Cherokee Nation Environmental Programs

Account Number: C162

Timothy Miller

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project:

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	01-01	Layered	Blue/White Texture	Asbestos Not Present	NA	CaCO3 Paint
001a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
002	01-02	Homogeneous	Blue/White Drywall	Asbestos Not Present	Cellulose 10 Glass Fiber 2	Gypsum Paint
003	01-03	Layered	Blue/White Texture	Asbestos Not Present	NA	CaCO3 Paint
003a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
004	02-01	Layered	White Joint Compound	Asbestos Not Present	NA	CaCO3
004a		Layered	White Drywall	Asbestos Not Present	Cellulose 10 Glass Fiber 2	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuanTEM Lab No. 382275

Client: Cherokee Nation Environmental Programs  
Timothy Miller

Account Number: C162

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project:

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
005	03-01	Layered	White Joint Compound	Asbestos Not Present	NA	CaCO3 Gypsum
005a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
006	04-01	Layered	Brown Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
006a		Layered	Clear Mastic	Asbestos Not Present	NA	Glue
007	05-01	Layered	White Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
007a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275  
 Account Number: C162  
 Date Received: 08/22/2025  
 Received By: Amanda Bass  
 Date Analyzed: 08/25/2025  
 Analyzed By: Tanner Smith  
 Methodology: EPA/600/R-93/116

Client: Cherokee Nation Environmental Programs  
 Timothy Miller

Project: \_\_\_\_\_  
 Project Location: Afton  
 Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
008	06-01	Layered	Gray/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint
008a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
009	06-02	Layered	Gray/Tan Texture	Asbestos Present Chrysotile <1	NA	CaCO3 Gypsum Paint
009a		Layered	Tan Joint Compound	Asbestos Not Present	NA	CaCO3 Gypsum
010	06-03	Homogeneous	Gray/White Texture	Asbestos Not Present	NA	CaCO3 Paint
011	07-01	Layered	Gray/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuanTEM Lab No. 382275	Client: Cherokee Nation Environmental Programs
Account Number: C162	Timothy Miller
Date Received: 08/22/2025	
Received By: Amanda Bass	
Date Analyzed: 08/25/2025	Project: _____
Analyzed By: Tanner Smith	Project Location: Afton
Methodology: EPA/600/R-93/116	Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
011a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
012	07-02	Homogeneous	Gray/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint
013	07-03	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
013a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
014	08-01	Homogeneous	Gray/Peach Drywall	Asbestos Not Present	Cellulose 10	Gypsum Paint
015	08-02	Homogeneous	Gray/White Drywall	Asbestos Not Present	Cellulose 10	Gypsum Paint
016	08-03	Layered	White Joint Compound	Asbestos Not Present	NA	CaCO3

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275  
 Account Number: C162

Client: Cherokee Nation Environmental Programs  
 Timothy Miller

Date Received: 08/22/2025  
 Received By: Amanda Bass  
 Date Analyzed: 08/25/2025  
 Analyzed By: Tanner Smith  
 Methodology: EPA/600/R-93/116

Project: \_\_\_\_\_  
 Project Location: Afton  
 Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
016a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
017	09-01	Homogeneous	White Caulk	Asbestos Not Present	NA	Glue Binder Paint
018	10-01	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 50 Glass Fiber 30	Perlite Paint
019	11-01	Layered	Tan Floor Tile	Asbestos Not Present	Synthetic 5	CaCO3 Vinyl
019a		Layered	Clear Mastic	Asbestos Not Present	NA	Glue
020	12-01	Homogeneous	Clear Caulk	Asbestos Not Present	NA	Glue Binder

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuanTEM Lab No. 382275	Client: Cherokee Nation Environmental Programs
Account Number: C162	Timothy Miller
Date Received: 08/22/2025	
Received By: Amanda Bass	
Date Analyzed: 08/25/2025	Project:
Analyzed By: Tanner Smith	Project Location: Afton
Methodology: EPA/600/R-93/116	Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
021	13-01	Homogeneous	White Caulk	Asbestos Not Present	NA	Glue Binder Paint
022	14-01	Layered	Yellow Formica	Asbestos Not Present	Cellulose 70	Resin Paint
022a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
023	15-01	Layered	Beige Texture	Asbestos Not Present	NA	CaCO3 Paint
023a		Layered	White Joint Compound	Asbestos Not Present	NA	CaCO3
023b		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
024	15-02	Layered	Beige Texture	Asbestos Not Present	NA	CaCO3 Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275

Client: Cherokee Nation Environmental Programs  
Timothy Miller

Account Number: C162

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project:

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
024a		Layered	Peach Drywall	Asbestos Not Present	Cellulose 10	Gypsum
025	15-03	Layered	Beige Texture	Asbestos Not Present	NA	CaCO3 Paint
025a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
026	16-01	Layered	Multi-Color Wall Paper	Asbestos Not Present	NA	Plastic Vinyl Binder
026a		Layered	White Mastic	Asbestos Not Present	NA	Glue
027	17-01	Layered	Tan/Gray Counter Top	Asbestos Not Present	NA	Clay Sand

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275	Client: Cherokee Nation Environmental Programs
Account Number: C162	Timothy Miller
Date Received: 08/22/2025	
Received By: Amanda Bass	
Date Analyzed: 08/25/2025	Project:
Analyzed By: Tanner Smith	Project Location: Afton
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
027a		Layered	Gray Grout	Asbestos Not Present	NA	CaCO3 Sand
027b		Layered	Off-white Mortar	Asbestos Not Present	Glass Fiber 15	Gypsum Sand Binder
027c		Layered	White Counter Top	Asbestos Not Present	Cellulose 70	Resin
027d		Layered	Tan Mastic	Asbestos Not Present	NA	Glue
028	18-01	Homogeneous	Multi-Color Liner	Asbestos Not Present	NA	Vinyl Binder Paint
029	19-01	Homogeneous	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
030	20-01	Homogeneous	Pink/White Drywall	Asbestos Not Present	Cellulose 10	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275

Client: Cherokee Nation Environmental Programs  
Timothy Miller

Account Number: C162

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project: \_\_\_\_\_

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
031	21-01	Layered	Silver Tile	Asbestos Not Present	NA	Glass Paint
031a		Layered	Tan Mastic	Asbestos Not Present	NA	Glue
032	22-01	Homogeneous	Clear Caulk	Asbestos Not Present	NA	Glue Binder
033	23-01	Layered	White/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint
033a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
034	23-02	Homogeneous	White/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

Quantem Lab No. 382275

Client: Cherokee Nation Environmental Programs

Account Number: C162

Timothy Miller

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project: \_\_\_\_\_

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
035	23-03	Homogeneous	White/Tan Texture	Asbestos Not Present	NA	CaCO3 Gypsum Paint
036	24-01	Layered	Gray Tile	Asbestos Not Present	NA	CaCO3 Vinyl
036a		Layered	Clear Mastic	Asbestos Not Present	NA	Glue
037	25-01	Layered	Brown Tile	Asbestos Not Present	NA	CaCO3 Vinyl
037a		Layered	Clear Mastic	Asbestos Not Present	NA	Glue
038	26-01	Layered	White Joint Compound	Asbestos Not Present	NA	CaCO3 Perlite
038a		Layered	Tan Drywall	Asbestos Not Present	Cellulose 10	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuanTEM Lab No. 382275

Client: Cherokee Nation Environmental Programs  
Timothy Miller

Account Number: C162

Date Received: 08/22/2025

Received By: Amanda Bass

Date Analyzed: 08/25/2025

Project: \_\_\_\_\_

Analyzed By: Tanner Smith

Project Location: Afton

Methodology: EPA/600/R-93/116

Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
039	27-01	Homogeneous	White Caulk	Asbestos Not Present	NA	Foam Binder
040	28-01	Homogeneous	Tan/White Joint Compound	Asbestos Not Present	NA	CaCO3 Perlite
041	29-01	Homogeneous	Tan/White Joint Compound	Asbestos Not Present	NA	CaCO3 Perlite
042	30-01	Homogeneous	White/Tan Caulk	Asbestos Not Present	NA	Glue Binder
043	31-01	Layered	Blue/White Joint Compound	Asbestos Not Present	NA	CaCO3
043a		Layered	Peach Drywall	Asbestos Not Present	Cellulose 10	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.  
NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods.  
This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.  
This report may not be reproduced except in full, without the written approval of the laboratory.



7021 W. Wilshire Blvd, Ste. B / Oklahoma City, OK 73132 / 405-755-7272

**Polarized Light Microscopy Asbestos Analysis Report**

QuantEM Lab No. 382275	Client: Cherokee Nation Environmental Programs
Account Number: C162	Timothy Miller
Date Received: 08/22/2025	
Received By: Amanda Bass	
Date Analyzed: 08/25/2025	Project: _____
Analyzed By: Tanner Smith	Project Location: Afton
Methodology: EPA/600/R-93/116	Project Number: N/A

QuantEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
044	32-01	Homogeneous	Gray Shingle	Asbestos Not Present	Cellulose 30	Tar CaCO3 Sand
045	33-01	Layered	White Siding	Asbestos Present Chrysotile 15	NA	CaCO3 Binder
045a		Layered	Black Siding	Asbestos Not Present	Cellulose 40	Tar Binder

Tanner Smith, Laboratory Analyst

8/26/2025

Date of Report

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuantEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



# ASBESTOS CHAIN OF CUSTODY

7021 W. Wilshire Blvd, Suite B, Oklahoma City, OK 73132  
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

For Lab Use Only	
Lab No. <u>382275</u>	
<input checked="" type="checkbox"/> Accept	<input type="checkbox"/> Reject

## LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Contact Information		Project Information		Report Results ( <input checked="" type="checkbox"/> one box )	
Company: Cherokee Nation Environmental Programs	Phone: (918) 207-4934	Project Name:		<input type="checkbox"/> QuanTEM Website	
Contact: Timothy Miller	Cell Phone: (918) 570-9545	Project Location: Afton		<input checked="" type="checkbox"/> Email <a href="mailto:timothy-miller@cherokee.org">timothy-miller@cherokee.org</a>	
Account #: C 162	E-mail: <a href="mailto:timothy-miller@cherokee.org">timothy-miller@cherokee.org</a>	Project ID:		<input type="checkbox"/> Other _____	
SAMPLED BY: Name: Timothy Miller	Date: 08/20/2025	P.O. Number: 895481			

RELINQUISHED BY	DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Timothy Miller	08/21/25@10AM	Fedex	<i>[Signature]</i>	8/22/25 10:15

### REQUESTED SERVICES (Please the Appropriate Boxes)

PLM	PLM	TEM	TEM	TURNAROUND TIME
<input checked="" type="checkbox"/> Bulk Analysis (EPA 600/R-93/116)	<input type="checkbox"/> Vermiculite Attic Insulation (EPA 600/R-04/004)	<input type="checkbox"/> Air- AHERA	<input type="checkbox"/> Bulk- Presence / Absence EPA600/R-93/116	<input type="checkbox"/> Rush
<input type="checkbox"/> 400 Point Count	<input type="checkbox"/> Other	<input type="checkbox"/> Air- NIOSH 7402	<input type="checkbox"/> Bulk- Quantitative (weight%)- Chatfield	<input type="checkbox"/> Same Day
<input type="checkbox"/> 1000 Point Count		<input type="checkbox"/> Air- ISO 10312	<input type="checkbox"/> Dust- Presence / Absence	<input type="checkbox"/> 24 - Hour
<input type="checkbox"/> Gravimetric Preparation	<b>PCM</b>	<input type="checkbox"/> Drinking Water- EPA 100.2	<input type="checkbox"/> Dust- Quantitative (fibers/sq.cm)- ASTM D5755	<input checked="" type="checkbox"/> 3 - Day
<input type="checkbox"/> Particle ID	<input type="checkbox"/> NIOSH 7400	<input type="checkbox"/> Waste Water- EPA 600/4-83-043	<input type="checkbox"/> Other	<input type="checkbox"/> 5 - Day

No.	Sample ID (10 Characters Max)	<input checked="" type="checkbox"/> To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	01-01	<input checked="" type="checkbox"/>	Blue	Wall and Ceiling Texture		Laundry Room
2	01-02	<input checked="" type="checkbox"/>	Blue	Wall and Ceiling Texture		Laundry Room
3	01-03	<input checked="" type="checkbox"/>	Blue	Wall and Ceiling Texture		Laundry Room
4	02-01	<input checked="" type="checkbox"/>	White	Wall Joint Compound Patch		Laundry Room (by door)
5	03-01	<input checked="" type="checkbox"/>	White	Wall Joint Compound Patch		Laundry Room ( behind washer)
6	04-01	<input checked="" type="checkbox"/>	Brown	Floor Tile		Office
7	05-01	<input checked="" type="checkbox"/>	White	Floor Tile		Office
8	06-01	<input checked="" type="checkbox"/>	Gray	Wall Texture		Office
9	06-02	<input checked="" type="checkbox"/>	Gray	Wall Texture		Office
10	06-03	<input checked="" type="checkbox"/>	Gray	Wall Texture		Office

**SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE** • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"  
 Please Note - UPS and USPS are **NOT** available for Saturday Delivery



# ASBESTOS CHAIN OF CUSTODY

7021 W. Wilshire Blvd, Suite B, Oklahoma City, OK 73132  
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

For Lab Use Only	
Lab No.	382275
<input checked="" type="checkbox"/> Accept	<input type="checkbox"/> Reject

**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Project Information						
Company: Cherokee Nation Environmental Programs			Project Name:		Project Location: Afton	
No.	Sample ID (10 Characters Max)	<input checked="" type="checkbox"/> To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
11	07-01	<input checked="" type="checkbox"/>	Gray	Ceiling Texture		Office
12	07-02	<input checked="" type="checkbox"/>	Gray	Ceiling Texture		Office
13	07-03	<input checked="" type="checkbox"/>	Gray	Ceiling Texture		Office
14	08-01	<input checked="" type="checkbox"/>	Gray	Wall Texture		Pantry/Office
15	08-02	<input checked="" type="checkbox"/>	Gray	Wall Texture		Pantry/Office
16	08-03	<input checked="" type="checkbox"/>	Gray	Wall Texture		Pantry/Office
17	09-01	<input checked="" type="checkbox"/>	White	Caulk (Baseboard)		Office
18	10-01	<input checked="" type="checkbox"/>	White	Ceiling Tiles		Throughout
19	11-01	<input checked="" type="checkbox"/>	Tan	Floor Vinyl Tiles		Bathroom 1
20	12-01	<input checked="" type="checkbox"/>	Clear	Caulk (Baseboard)		Bathroom 1
21	13-01	<input checked="" type="checkbox"/>	White	Caulk (Baseboard)		Bathroom 1
22	14-01	<input checked="" type="checkbox"/>	Yellow	Formica		Bathroom 1
23	15-01	<input checked="" type="checkbox"/>	Beige	Wall and Ceiling Texture		Bathroom 1
24	15-02	<input checked="" type="checkbox"/>	Beige	Wall and Ceiling Texture		Bathroom 1
25	15-03	<input checked="" type="checkbox"/>	Beige	Wall and Ceiling Texture		Bathroom 1
26	16-01	<input checked="" type="checkbox"/>	Camo	Wallpaper		Kitchen
27	17-01	<input checked="" type="checkbox"/>	Tan	Counter-top		Kitchen
28	18-01	<input checked="" type="checkbox"/>	Multi	Sink Shelf Liner		Kitchen
29	19-01	<input checked="" type="checkbox"/>	White	Drywall		Kitchen
30	20-01	<input checked="" type="checkbox"/>	Pink	Drywall		Bathroom 2

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"  
 Please Note - UPS and USPS are NOT available for Saturday Delivery



## ASBESTOS CHAIN OF CUSTODY

7021 W. Wilshire Blvd, Suite B, Oklahoma City, OK 73132  
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

For Lab Use Only	
Lab No. <u>382275</u>	
<input checked="" type="radio"/> Accept	<input type="radio"/> Reject

Project Information						
Company: Cherokee Nation Environmental Programs			Project Name:		Project Location: Afton	
No.	Sample ID (10 Characters Max)	<input checked="" type="checkbox"/> To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
31	21-01	<input checked="" type="checkbox"/>	Mirror	Glass Wall Tile		Bathroom 2
32	22-01	<input checked="" type="checkbox"/>	Caulk	Clear		Bathroom 2
33	23-01	<input checked="" type="checkbox"/>	White	Ceiling Texture		Bathroom 2
34	23-02	<input checked="" type="checkbox"/>	White	Ceiling Texture		Bathroom 2
35	23-03	<input checked="" type="checkbox"/>	White	Ceiling Texture		Bathroom 2
36	24-01	<input checked="" type="checkbox"/>	Gray	Vinyl Tile		Bathroom 2
37	25-01	<input checked="" type="checkbox"/>	Brown	Vinyl Tile		Bathroom 2
38	26-01	<input checked="" type="checkbox"/>	White	Joint Compound		HVAC Closet
39	27-01	<input checked="" type="checkbox"/>	White	Caulk (Plenum)		HVAC Closet
40	28-01	<input checked="" type="checkbox"/>	Tan	Joint Compound (Wall)		Bedroom 1
41	29-01	<input checked="" type="checkbox"/>	Tan	Joint Compound (Window Sill)		Bedroom 1
42	30-01	<input checked="" type="checkbox"/>	White	Caulk (Window)		Living Room
43	31-01	<input checked="" type="checkbox"/>	Blue	Drywall		Living Room
44	32-01	<input checked="" type="checkbox"/>	Gray	Shingles		Roof
45	33-01	<input checked="" type="checkbox"/>	White	Siding		Exterior
46		<input type="checkbox"/>				
47		<input type="checkbox"/>				
48		<input type="checkbox"/>				
49		<input type="checkbox"/>				
50		<input type="checkbox"/>				

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"  
 Please Note - UPS and USPS are **NOT** available for Saturday Delivery