
EXHIBIT A- DWIGHT MISSION ROOF REPLACEMENT



WALTON DINING HALL-NORTH DAMAGE



WALTON DINING HALL-SOUTH DAMAGE



EPDM ROOF (TOP, NOT SHOWN) ON FLAT ROOF. INCLUDE FLASHINGS AS REQUIRED AT ALL TRANSITIONS.

NEW ASPHALT SHINGLE ROOF OVER ADDED LAYER OF DECKING OVER REPAIRED DECKING. ADDED DECKING SHALL BE THICKNESS SUFFICIENT TO PREVENT ROOF NAILS FROM PROTRUDING UNDERSIDE.

HardieShingle STRAIGHT FAUX SIDING ON VERTICAL FACE. INCLUDE FLASHINGS AS REQUIRED AT TRANSITIONS.

DORM PORCHES (TYPICAL SAGE AND WASHBURN HALL)



UNDERSIDE OF DORM PORCHES, TYPICAL BOTH DORMS. REPAIR DECKING AS REQUIRED UNDER UNIT COST. ADD DECKING UNDER SHINGLE ROOF AREAS SUFFICIENT TO PREVENT ROOF NAILS FROM PROTRUDING UNDERSIDE. REPAIR DAMAGED STRUCTURAL MEMBERS.

DORM PORCHES (TYPICAL SAGE AND WASHBURN HALL)