918.587.2282 | F 918.587.2285

SELSER SCHAEFER ARCHITECTS

Project Name:	Cherokee Nation Entertainment Cherokee Tower Renovation	Item Number:	UPH-ACC12
Issue Date:	10/2/13	Item Description:	Fabric for ACC12 Bed Pillow Cover
Revision(s):	Issue 02	Area Name:	Honeymoon Suite

Item Pricing:	\$/ yard	Total Quantity:	5.25 yards (actual fabrication)
Manufacturer:	Fabricut	Source:	Kathleen Hughs, Inc.
Address:	9303 E 49th St Tulsa, Oklahoma 74145	Address:	4220 Windhaven Lane Dallas, Texas 75287
Phone	800.999.5533	Phone	972.250.3630
Fax	918.665.1177	Fax	972.250.3749
Contact	See Source	Contact	Kathy Hughs
Email	contract@fabricut.com	Email	kathy@kathleenhughs.com
Web	www.contractfabricut.com	Web	www.kathleenhughs.com

Description:

Upholstery fabric for decorative bed pillow cover Refer to ACC12

Upholstery	
Fabric Quantity:	1 yard
Fabric Manufacturer:	Fabricut
Fabric Pattern Name:	Opulent
Fabric Color Name:	32
Fabric Width:	54″
Fabric Repeat:	None
Fabric Content:	51% Polyester, 49% Acrylic
Average Bolt:	55 Yards
Double Rubs:	66,000
Fire Rating:	NFPA 260A
Flame Retardant:	None
Backing:	None
Finish:	None
Cleaning Method:	Cleaning Code - S

Lead Time 6-8 weeks

 Required Item(s) for Designer Approval Prior to Fabrication:

 □ Seaming Diagram
 □ Strike-Off
 ⊠ Finish Sample
 □ Cutting
 □ Shop Dwgs
 □ Prototype
 □ Flame Certificate
 □ Other...

Instructions:

- Quantity shown reflects the actual amount of fabric used to manufacturer pillow covers. Required yardage may vary

918.587.2282 | F 918.587.2285

Project Name:	Cherokee Nation Entertainment Cherokee Tower Renovation	Item Number:	UPH-ACC12
Issue Date:	10/2/13	Item Description:	Fabric for ACC12 Bed Pillow Cover
Revision(s):	Issue 02	Area Name:	Honeymoon Suite

SELSER	SCHAEFER	ARCHITECTS
--------	----------	------------

Item Pricing: \$ yard	Total Quantity:	5.25 yards (actual fabrication)
Manufacturer: Fabricut	Source:	Kathleen Hughs, Inc.

from workroom to workroom. Fabricator should coordinate additional quantities required for proper cutting, seaming, waste, etc. with Owner.

- Quantity does not account for attic stock. Fabricator should coordinate with Owner.

- Install per manufacturers recommendations.

