

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment
Cherokee Tower Renovation

Item Number: UPH-ACC2

Issue Date: 10/2/13

Item Description: Fabric for ACC2 bed pillow cover

Revision(s): Issue 02

Area Name: Standard King, Ada King, Deluxe King
Suite, Deluxe King Mini Suite

Item Pricing: yard	Total Quantity: 50.25 yards (actual fabrication)
Manufacturer: Fabricut	Source: Kathleen Hughs, Inc.
Address: 9303 E 49th St Tulsa, Oklahoma 74145	Address: 4220 Windhaven Lane Dallas, Texas 75287
Phone: 800.999.5533	Phone: 972.250.3630
Fax: 918.665.1177	Fax: 972.250.3749
Contact: See Source	Contact: Kathy Hughs
Email: contract@fabricut.com	Email: kathy@kathleenhughsinc.com
Web: www.fabricutcontract.com	Web: www.kathleenhughsinc.com

Description: Upholstery fabric for machine washable bed pillow cover
Refer to ACC2

Upholstery
Fabric Manufacturer: Fabricut
Fabric Pattern Name: Bolero
Fabric Color Name: Jet
Fabric Width: 54"
Fabric Repeat: None
Fabric Content: 100% Polyester
Average Bolt: 40 Yards
Double Rubs: 48,000
Fire Rating: NFPA 260A
Flame Retardant: None
Backing: None
Finish: None
Cleaning Method: Cleaning Code - S

Lead Time 8-10 weeks

Required Item(s) for Designer Approval Prior to Fabrication:

Seaming Diagram Strike-Off Finish Sample Cutting Shop Dwgs Prototype Flame Certificate Other...

Instructions:

- Quantity shown reflects the actual amount of fabric used to manufacturer pillow covers. Required yardage may vary from workroom to workroom. Fabricator should coordinate additional quantities required for proper cutting, seaming, waste, etc. with Owner.

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment
Cherokee Tower Renovation

Item Number: UPH-ACC2

Issue Date: 10/2/13

Item Description: Fabric for ACC2 bed pillow cover

Revision(s): Issue 02

Area Name: Standard King, Ada King, Deluxe King
Suite, Deluxe King Mini Suite

Item Pricing: yard

Total Quantity: 50.25 yards (actual fabrication)

Manufacturer: Fabricut

Source: Kathleen Hughs, Inc.

- Quantity does not account for attic stock. Fabricator should coordinate with Owner.
- Install per manufacturers recommendations.

