			SELSER SCHAEFER ARCHITECTS			
Project Name:	Cherokee Nation		Item Number:	UPH-ACC8		
Issue Date:	10/2/13		Item Description:	Fabric for ACC8 Chair Pillow Cover		
Revision(s):	Issue 02		Area Name:	Honeymoon Suite		
Item Pricing:	/ yard		Total Quantity:	1.5 yards (actual fabrication)		
Manufacturer:	Fabricut		Source:	Kathleen Hughs, Inc.		
Address:	9303 E 49th St Tulsa, Oklahoma 74145		Address:	4220 Windhaven Lane Dallas, Texas 75287		
Phone	800.999.5533		Phone	972.250.3630		
Fax	918.665.1177		Fax	972.250.3749		
Contact	See Source		Contact	Kathy Hughs		
Email	contract@fabricut.com		Email	kathy@kathleenhughs.com		
Web	www.contractfabr	icut.com	Web	www.kathleenhughs.com		
Description:		Upholstery fabric for Refer to ACC8	decorative bed pillov	v cover		
Fabric Manufacturer: Fabric Pattern Name: Fabric Color Name: Fabric Width: Fabric Repeat: Fabric Content: Average Bolt: Double Rubs: Fire Rating: Flame Retardant: Backing: Finish: Cleaning Method:		Fabricut Enovy Sienna 54" None 100% Polyester Inhe 55 Yards 75,000 NFPA 701 None None None Cleaning Code - S	erent			
Lead Time	4-5 weeks					
Required Item	(s) for Designer	Approval Prior to Fa	ıbrication:			
☐ Seaming Diagram ☐ Strike-Off ☑ Finish Sample ☐ Cutting ☐ Shop Dwgs ☐ Prototype ☐ Flame Certificate ☐ Other						

Instructions:

Page 1 UPH-ACC8

⁻ Quantity shown reflects the actual amount of fabric used to manufacturer pillow covers. Required yardage may vary from workroom to workroom. Fabricator should coordinate additional quantities required for proper cutting, seaming, waste, etc. with Owner.

918.587.2282 | F 918.587.2285

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment

Cherokee Tower Renovation

UPH-ACC8 Item Number:


10/2/13 Issue Date:

Item Description: Fabric for ACC8 Chair Pillow Cover

Issue 02 Revision(s): Area Name: **Honeymoon Suite**

Item Pricing: \$/ yard	Total Quantity:	1.5 yards (actual fabrication)
Manufacturer: Fabricut	Source:	Kathleen Hughs, Inc.

- Quantity does not account for attic stock. Fabricator should coordinate with Owner. - Install per manufacturers recommendations.



Page 2 UPH-ACC8