SELSER SCHAEFER ARCHITECTS

Project Name:	Cher	okee	Nation	Enterta	inment

Cherokee Tower Renovation

Item Number: UPH-ACC9

Issue Date: 10/2/13

Item Description: Fabric for ACC9 Chair Pillow Cover

Revision(s): Issue 02 Area Name: Honeymoon Suite

Item Pricing:	\$ yard	Total Quantity:	.5 yards (actual fabrication)
Manufacturer:	Fabricut	Source:	Kathleen Hughs, Inc.
Address:	9303 E 49th St Tulsa, Oklahoma 74145	Address:	4220 Windhaven Lane Dallas, Texas 75287
Phone	800.999.5533	Phone	972.250.3630
Fax	918.665.1177	Fax	972.250.3749
Contact	See Source	Contact	Kathy Hughs
Email	contract@fabricut.com	Email	kathy@kathleenhughs.com
Web	www.contractfabricut.com	Web	www.kathleenhughs.com

Description: Upholstery fabric for decorative bed pillow cover

Refer to ACC9

Upholstery

Fabric Manufacturer: Fabricut
Fabric Pattern Name: Opulent
Fabric Color Name: Ivory
Fabric Width: 54"
Fabric Repeat: None

Fabric Content: 51% Polyester, 49% Acrylic

Average Bolt: 55 Yards
Double Rubs: 66,000
Fire Rating: NFPA 260A
Flame Retardant: None
Backing: None
Finish: None

Cleaning Method: Cleaning Code - S

Lead Time	6-8 weeks			
Required Item(s) for Designer Approval Prior to Fabrication:				
☐ Seaming Diagram	n □ Strike-Off ☑ Finish Sample ☑ Cutting □ Shop Dwgs □ Prototype □ Flame Certificate □ Other			
Instructions:				

- Quantity shown reflects the actual amount of fabric used to manufacturer pillow cover. Required yardage may vary from workroom to workroom. Fabricator should coordinate additional quantities required for proper cutting, seaming,

Page 1 UPH-ACC9

918.587.2282 | F 918.587.2285

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment

Cherokee Tower Renovation

UPH-ACC9 Item Number:

10/2/13 Issue Date:

Item Description: Fabric for ACC9 Chair Pillow Cover

Revision(s): Issue 02 Area Name: **Honeymoon Suite**

Item Pricing: \$ yard	Total Quantity:	.5 yards (actual fabrication)
Manufacturer: Fabricut	Source:	Kathleen Hughs, Inc.

waste, etc. with Owner.

Quantity does not account for attic stock. Fabricator should coordinate with Owner.
Install per manufacturers recommendations.



Page 2 UPH-ACC9