

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment
Cherokee Tower Renovation

Item Number: UPH-FURN43

Issue Date: 10/2/13

Item Description: Fabric for FURN43 lounge chair

Revision(s): Issue 02

Area Name: Honeymoon Suite

Item Pricing: / yard	Total Quantity: 6 yards
Manufacturer: Fabricut	Source: Kathleen Hughs, Inc.
Address: 9303 E 49th St Tulsa, Oklahoma 74145	Address: 4220 Windhaven Lane Dallas, Texas 75287
Phone: 800.999.5533	Phone: 972.250.3630
Fax: 918.665.1177	Fax: 972.250.3749
Contact: See Source	Contact: Kathy Hughs
Email: contract@fabricut.com	Email: kathy@kathleenhughsinc.com
Web: www.fabricutcontract.com	Web: www.kathleenhughsinc.com

Description: Upholstery fabric for lounge chair
Refer to FURN43

Upholstery
Fabric Quantity: 5-1/2 yards
Fabric Manufacturer: Fabricut
Fabric Pattern Name: Opulent
Fabric Color Name: 32
Fabric Width: 54"
Fabric Repeat: None
Fabric Content: 51% Polyester, 49% Acrylic
Average Bolt: 55 Yards
Double Rubs: 66,000
Fire Rating: NFPA 260A
Flame Retardant: None
Backing: None
Finish: None
Cleaning Method: Cleaning Code - S

Lead Time 6-8 weeks

Required Item(s) for Designer Approval Prior to Fabrication:

Seaming Diagram Strike-Off Finish Sample Cutting Shop Dwgs Prototype Flame Certificate Other...

Instructions:

- Quantity shown reflects the actual amount of fabric Carson's Hospitality requires for upholstering the Thoughtful series lounge chair. This quantity is subject to change if the specified chair is substituted. Required yardage may vary from

SELSER SCHAEFER ARCHITECTS

Project Name: Cherokee Nation Entertainment
Cherokee Tower Renovation

Item Number: UPH-FURN43

Issue Date: 10/2/13

Item Description: Fabric for FURN43 lounge chair

Revision(s): Issue 02

Area Name: Honeymoon Suite

Item Pricing: \$ / yard

Total Quantity: 6 yards

Manufacturer: Fabricut

Source: Kathleen Hughs, Inc.

workroom to workroom. Fabricator should coordinate additional quantities required for proper cutting, seaming, waste, etc. with Owner.

- Quantity does not account for attic stock. Fabricator should coordinate with Owner.
- Install per manufacturers recommendations.

