WorkWrite-Up and Bid Document/By Trade

John Griffith	Contractor Signature:		1		
604 Byrd Avenue Sallisaw, OK 7-4955 (918) 208-6945					
(6.0) 200 00 10			This document must be signed to be a valid bid.		
PR			Bid Due Date:		
Trade Work Description /	' Comments		Gen. Spec.	Qty Unit	Item Bid
Carpentry			771		
1 Area: KITCHEN			<i>Div.</i> # 10.G	1 Ea	
Fire Extinguisher/Install. Install new fire extin	guisher.				
Electrical				,	
2 Area: INTERIOR			<i>Div.</i> # 13.D. 11	5 Ea -	
Smoke Detector/Battery Operated/Install new lithium battery). All bedrooms and hallways a written approved equal.					landari de la constitución de la
Install in kitchen, hallway and all bedrooms.		_ >	n		
HVAC	-				
3 Area: GARAGE			<i>Div.</i> # 12	1 Ea	
HVAC Equipment/Central/Cooling/ Heating/3 equipment (13 SEER). INSIDE FURNACE A			0		
COIL, EVAP, NEW DISCONNECT, NEW HI Change out.					
Plumbing			9	V V	

Print Date: Friday, July 6, 2018

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing				
Area: GARAGI		Div.# 11.A	1 Ea	
al. gas water heate	O Gallon/Replace. Replace existing gas water er. Work shall include elevating to 18" (if in gar air, gas & electrical hook-ups for code legal in	age), replacement of		
oofing				
Area: ROOF		Div.#7.A.	26 Sq	
Pipe Flashing, Valle	rkey/Tamko or written approved equal. 30 lb For y Flashing. e shingles, contractor is responsible for remove			
Area: ROOF		<i>Div.</i> # 7.A	96 SF	
Sheathing/5/8" CDX	(/Replace. Replace existing sheathing/Use 5/8)	" CDX.		
Replace all deterior	ated decking.			
installation proce Based Paint requi compliance with t for conducting sa Workers. Asbesto	hall be in accordance with local codes, mandures, good quality workmanship practices rements when applicable. Conflicts between the more stringent requirement. Contractor fe work practices that comply with OSHA Cost report, where required, will be attached its Sampling Report for location and testing	s, General Specifications a en requirements will be re- awarded the job will be re- construction Standards for f areas tested are 1% or gr	nd Lead- solved by sponsible Asbestos eater. See	al:

John Griffith-site directions, highway 59 to Sallisaw turn left on East Redwood Street, then left at Sam Ed Bush Dr.

604 Byrd Avenue, Sallisaw Ok. 74955

Phone #918-208-6945