CHEROKEE NATION Environmental Programs



Asbestos Sampling Report

PREPARED BY:

Logan Girty

__DATE: 1/21/2025

LOGAN GIRTY. ENVIRONMENTAL SPECIALIST III

REQUESTED BY: HACN HOUSING REHABILITATION (HUD) -

GEORGE HUBBARD

TABLE OF CONTENTS

- I. SITE INSPECTION/DESCRIPTION
- II. BACKGROUND
- III. FIELD PROCEDURES AND ANALYTICAL METHODS
- IV. SUMMARY OF FINDINGS
- V. CONCLUSIONS

APPENDIX A: PROJECT SCOPE OF WORK

APPENDIX B: LABORATORY REPORT & CHAIN OF CUSTODY

I. Site Inspection/Description

Cherokee Nation Environmental Programs (CNEP) has conducted asbestos sampling for the presence of asbestos containing materials (ACM) for the following site:

43410 S 646 Rd, Jay, OK 74346 918-353-5275

Coordinates: 36.3881 / -94.7262

The sampling was performed to determine the presence of all ACM from within the affected parts of the structure for EPA's National Emissions of Hazardous Air Pollutants (NESHAP) compliance as well as OSHA worker protection.

The inspector responsible for this project was:

Logan Girty, AHERA Inspector

The sampling was conducted on January 7, 2025 at the request of the Cherokee Nation Housing Rehabilitation Department.

The site is a single family home built in 1970. Sampling was limited to areas that would be affected by the project scope of work (Appendix A) provided by the housing rehabilitation department.

ACM was found at this site. See Section IV for locations.

II. BACKGROUND

The Oklahoma Department of Environmental Quality (ODEQ) has adopted EPA's NESHAP regulation under OAC252:100, 41-15 and has been delegated authority in the state of Oklahoma for its enforcement. Section 61.145(a) of Federal EPA regulation states that prior to commencement of the demolition or renovation of a facility a thorough inspection of the affected part or parts of a facility is required to determine the presence of all asbestos including Category I and Category II non-friable, and friable ACM. ACM is defined by EPA and OSHA as any material that contains greater than 1% asbestos.

III. FIELD PROCEDURES AND ANALYTICAL METHODS

During the on-site inspection, we visually assessed the physical characteristics of suspect asbestos-containing materials (SACM) based on homogeneous areas. Homogeneous areas are areas of asbestos similar in color, texture, and construction, date of application, and in general

appearance. For purposes of renovation and demolition, homogeneous areas of SACM can be further classified according to NESHAPs rules by whether the material is friable, Category I non-friable, or Category II non-friable.

<u>Friable ACM</u> is defined by NESHAPs rules as any material containing more than 1% asbestos as determined by Polarized Light Microscopy (PLM), that, when dry, can be crumbled, pulverized or reduced to powder by hand pressure.

<u>Category I Non-friable ACM</u> is defined by NESHAPs rules as any asbestos-containing packings, gaskets, construction mastics, resilient floor covering (i.e. floor tiles, roll sheet flooring) or asphalt roofing products that contain more than 1% asbestos as determined by PLM.

<u>Category II Non-friable ACM</u> is defined by NESHAPs rules as any material, excluding Category I non-friable ACM, containing more than 1% asbestos as determined by PLM, when dry, cannot be crumbled, pulverized, or reduced to powder by hand pressure.

Typically, non-friable materials, such as transite (cementious products) and vinyl floor tiles are not regulated by the State of Oklahoma provided they do not become friable. General deterioration, machine grinding, drilling, sanding, and dry-buffing are all ways of causing non-friable materials to become classified as Regulated Asbestos Containing Materials (RACM). All friable materials are classified RACM. Please note that the following materials, even though classified as non-friable are fully regulated by Oklahoma Department of Labor for removal purposes as friable material: ceiling tiles, roll sheet flooring (linoleum), and joint wall compound when deemed friable

In addition to classification of suspect material into friable and non-friable materials, a determination of current condition was conducted as part of the physical assessment. The condition noted is the representative of the material at the time of inspection. Conditions of materials can change very quickly when disturbed. All suspect material was placed in one of the following categories of condition.

<u>Significantly damaged</u>: Material that is damaged, blistered, deteriorated, water stained over at least 10% of its total area.

<u>Damaged</u>: Material that is damaged, blistered, deteriorated, water stained less than 10% of its total area.

Good: Material that has no visible damage or deterioration.

Guidelines used for the number of samples collected per homogeneous area were determined using the Asbestos Hazard Emergency Response Act (AHERA) protocol promulgated in 40 CFR 763, Appendix E as follows:

Surfacing materials – material that is sprayed or troweled on wall, ceilings, or support columns for fireproofing, acoustical, or even decorative purpose.

- Less than 1000 ft2 Minimum 3 samples
- From 1000-5000 ft2 Minimum 5 samples
- Greater than 5000 ft2 Minimum 7 samples

Thermal System Insulation (TSI) materials – thermal system insulation material applied to tanks, boiler, pipes or other structural component for an insulating purpose.

- May omit areas of fibrous glass, foam glass, rubber, and Styrofoam form sampling.
 Areas that have mastic on seams or outer jacketing will be sampled.
- At least three samples must be collected from each homogeneous area of TSI.
- Plus an additional sample from each patched area of less than 6 linear feet.
- Fittings require a sufficient amount to determine positive or negative nature.
- Inspector will first collect samples from damaged areas, exposed ends, or areas missing jacketing first.

Miscellaneous materials – all other material that are not thermal system insulation or surfacing materials. This includes gaskets, packings, joint wall compound, cementious asbestos materials, ceiling tiles resilient flooring materials, construction mastics, etc..

- May assume and document as such
- A sufficient amount of samples to determine negative or positive nature. A minimum or one per suspect homogeneous area.
- Collect samples from inconspicuous locations.
- Material such as cementious asbestos or vibration dampening cloths should not be sampled and will be assumed ACM unless instructed by client to collect these samples.

Bulk samples of suspect ACM were analyzed by Polarized Light Microscopy (PLM) in accordance with EPA Methods 600R-93/116. All samples were sent to a NVLAP accredited laboratory for analysis. QuanTEM Laboratories, LLC (NVLAP # 101959-0) in Oklahoma City, OK analyzed the samples. A copy of the full laboratory report and chain of custody can be found in Appendix B.

IV. SUMMARY OF FINDINGS

A total of 13 samples were analyzed from 3 homogeneous areas due to multi-layers of material within some homogeneous sample areas. All accessible and observable areas within the renovation area were sampled for ACM. Samples were not taken of suspect materials that may have placed the inspector at risk of injury (i.e. electrical panel boxes). Any suspect ACM that have not been tested and/or found positive for asbestos must be assumed ACM until they are analyzed. Upon review of laboratory analysis, the following asbestos containing materials can be found in Table 1. All suspect ACM samples that were analyzed and did not contain asbestos can be found in Table 2.

Sample #	Material Description	Locations	Friability (Friable, NF Cat I NF Cat II)	Condition	Sample Results (% Asbestos)
01-01					
01-02					
01-03					
01-04	Drywall Texture	Throughout	Friable	Damaged	3% Chrysotile
01-05				J	SUAPASE INCHES PROPERTY
01-06					
01-07					
02-01					
02-02					
02-03	Popcorn Ceiling Texture	Throughout	Friable	Damaged	5% Chrysotile
02-04	1	Thoughout	Triable	Damaged	376 Cmysothe
02-05					

Table 2. N	Non – Asbestos Containing Ma	terials		
Sample #	Material Description	Locations	Condition	Sample Results (% Asbestos)
03-01	Shingle	Roof	Damaged	None Detected

V. CONCLUSIONS

Asbestos is not always an immediate hazard. Intact and undisturbed ACM does not pose a health risk. They may, however become a health hazard if they are damaged, disturbed, or deteriorate over time and release fibers into the air. There are no federal, state, or Tribal laws mandating asbestos removal. It is only when the material can no longer be maintained in good condition and/or airborne concentrations of asbestos are measured and found to be above a permissible exposure limit (PEL), or when the building is to be demolished or renovated, that removal may become necessary. Any renovation/demolition work which may impact these positive materials should be conducted in accordance with all applicable Federal, state, and local regulations.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120

1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 375660

Account Number:

C162

Date Received:

01/16/2025

Received By:

Amanda Bass

Date Analyzed:

01/20/2025

Analyzed By: Methodology: Cassie Sanborn

EPA/600/R-93/116

Client: Cherokee Nation Environmental Programs

Logan Girty PO Box 948

Tahlequah, OK 74464

Project Location: Jay Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrou
001	01-01	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
001a		Layered	White Drywall	Asbestos Not Present	Cellulose	3 Gypsum
002	01-02	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
002a		Layered	White Texture	Asbestos Present Chrysotile 3	NA	CaCO3 Paint
003	01-03	Homogeneous	White Texture	Asbestos Not Present	NA	CaCO3 Paint
004	01-04	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
004a		Layered	White Drywall	Asbestos Not Present	Cellulose 10) Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 375660

Account Number:

C162

Date Received:

01/16/2025

Received By:

Amanda Bass

Date Analyzed:

01/20/2025

Analyzed By: Methodology: Cassie Sanborn

EPA/600/R-93/116

Client: Cherokee Nation Environmental Programs

Logan Girty

PO Box 948

Tahlequah, OK 74464

Project Location: Jay Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrou
005	01-05	Layered	White Texture	Asbestos Present Chrysotile <1	NA	CaCO3 Paint
005a		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
006	01-06	Homogeneous	White Texture	Asbestos Not Present	NA	CaCO3 Paint
007	01-07	Homogeneous	White Texture	Asbestos Present Chrysotile <1	NA	CaCO3 Paint
008	02-01	Homogeneous	Tan Ceiling Texture	Asbestos Present Chrysotile 5	NA	CaCO3 Foam Paint
009	02-02	Homogeneous	Tan Ceiling Texture	Asbestos Present Chrysotile 5	NA	CaCO3 Foam Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120

1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 375660

Account Number:

C162

Date Received:

01/16/2025

Received By:

Amanda Bass

Date Analyzed:

01/20/2025

Analyzed By: Methodology: Cassie Sanborn

EPA/600/R-93/116

Client: Cherokee Nation Environmental Programs

Logan Girty PO Box 948

Tahlequah, OK 74464

Project Location: Jay Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)		Non-Asbestos Fiber (%)	Non Fibrous
010	02-03	Homogeneous	Tan Ceiling Texture	Asbestos Present Chrysotile	5	NA	CaCO3 Foam Paint
011	02-04	Homogeneous	Tan Ceiling Texture	Asbestos Present Chrysotile	5	NA	CaCO3 Foam Paint
012	02-05	Homogeneous	Tan Ceiling Texture	Asbestos Present Chrysotile	5	NA	CaCO3 Foam Paint
013	03-01	Homogeneous	Black Shingle	Asbestos Not Present		Cellulose	30 Tar Sand

Cassie Sanboy

Cassie Sanborn, Laboratory Analyst

1/20/2025 Date of Report

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.



ASBESTOS CHAIN OF CUSTODY

Page 1 of 2

For Lab Use Only

Lab No.

Reject

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502 (800) 822-1650 • (405) 755-2272 • Fax: (405) 755-2058

>
~
_
17
\sim
щ
-
PRINT
~
-
000
Δ.
-
ш
S
-
-
_
Ω.
•
_
-
-
ш
5
\supset
U
×
0
4
U
ш
-

	THE RESERVE OF THE PARTY OF THE	Contact Information	nation			The state of the s	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAM	Proio	Project Information	•	Concert Dogs	(und and hall) sale
		C Lotacomacai			100	07.70			COUNTY OF THE CO		Seport Res	Aceport Results (one box)
Company:	y: Cherokee Nation Environmental Programs	/Ironmental Pr	_	Phone: (9	18)	(918) 453-6140					Quani	QuanTEM Website
Contact:	Logan Girty			Cell Phone: (918) 772-8346	18) 7		Project Location: Jay	^		-	✓ Email	Email logan-girty@cherokee.org
Account #:	# C 162			E-mail: logan-ç	girty@	logan-girty@cherokee.org	Project ID:				Other	
SAMPLE	SAMPLED BY: Name: Logan Girty	ty.		Date: 1/7/2025	2025		P.O. Number: 89	895481			1	
)	RELINQUISHED BY	D BY		DATE & TIME	IME	VIA	A		RECEIVED BY	D BY		DATE & TIME
}	Den 8. 19		7	1/8/25 @ 9	@ 9 AM	1 FedEx	Ex	1	12	7	//	20:626/01/
0	0										-	
				REQUESTE	D SE	WICES (Pleas	ESTED SERVICES (Please the Appropriate Boxes)	opriate	Boxes)			
	PLM		PLM			TEM			TEM		TURN	TURNAROUND TIME
<u>я</u>	Bulk Analysis (EPA 600/R-93/116)	Vermiculi	Vermiculite Attic Insulation	lation		Air- AHERA			Bulk- Presence / Absence EPA600/R-93/116	EPA600/R-93/116		Rush
☐ A	400 Point Count	Other	R-04/004			Air-NIOSH 7402		m m	Bulk-Quantitative [weight%]- Chatfield	t%]- Chatfield		Same Day
_	1000 Point Count					Air- ISO 10312		Sna	Dust- Presence / Absence			24 - Hour
Ū	Gravimetric Preparation		PCM			Drinking Water- EPA 100.2	PA 100.2	Dus	Dust-Quantitative [fibers/sq.cm]- ASTM D5755	'sq.cm]- ASTM D5755	<u>\</u>	3 - Day
	Particle ID	NIOSH 7400	00			Waste Water- EPA 600/4-83-043	600/4-83-043	Other	er			5 - Day
No.	Sample ID	☑ To Be Co Analyzed	Color			Description	uo		Volume / Area (as applicable)	Comm	Comments / Notes	tes
-	01-01	✓ WF	White			Drywall Texture	dure			Thr	Throughout	
2	01-02	Wh.	White			Drywall Texture	dure			Thr	Throughout	
m	01-03	Wh	White			Drywall Texture	dure			The	Throughout	
4	01-04	W	White			Drywall Texture	dure			Thr	Throughout	
2	01-05	Wh Wh	White			Drywall Texture	dure			Thr	Throughout	
9	01-06	<u>\</u>				Drywall Texture	dure			Thr	Throughout	
7	01-07	<u>\</u>				Drywall Texture	dure			Thr	Throughout	

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package 'Hold for Saturday Pickup' Throughout Please Note - UPS and USPS are NOT available for Saturday Delivery

Popcorn Ceiling Texture Popcorn Ceiling Texture Popcorn Ceiling Texture

2 Z

02-01

8 6 5

Throughout Throughout



ASBESTOS CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

			\neg
N	1	B	Reject
of	e Only	3	ě
7	O Use	7	da
Page	For Lab Use Or	ab No. 2	Ago Ago
		Lab	

Proj	Project Information						
Company:		on Environm	Cherokee Nation Environmental Programs	10	Project Location: Jay	Jay	
No.	Sample ID (10 Characters Max)	☑ To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes	
=	02-04	>		Popcorn Ceiling Texture		Throughout	
12	02-05	>		Popcorn Ceiling Texture		Throughout	
13	03-01	>		Shingle		Roof	
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE . Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 . Mark Package "Hold for Saturday Pickup" Please Note - UPS and USPS are NOT available for Saturday Delivery