

# HACN HOUSING REHAB SITE DIRECTIONS

Name: <u>Grover Hendrickson</u> Telephone: <u>(918)316-4426</u>

Address: 16

1616 clayton Dr

tahlequah, OK 74465

County: Cherokee

Year Built: 1960

GPS Coordinates: 35.93327,-94.98374 Drive Time: 15MIN



**Directions:** From Cherokee Nation, Head northeast on US-62/S Muskogee Ave toward S Cotton Wood St 0.7 mi At the traffic circle, take the 2nd exit and stay on US-62/S Muskogee Ave 2.3 mi Turn left onto OK-51 W/OK-51BYP 3.1 mi Continue onto OK-51 Spur 0.7 mi Turn right onto W Allen Rd 0.9 mi Turn left onto N Sleepy Hollow Ln 0.2 mi Turn right onto Clayton Dr Destination will be on the left 272 ft

1616 Clayton Dr.

Larry Ketcher	5/15/2025	
Cost Estimator/Inspector	Date	



escription	-		Quantity	Per
TIMATE: Emergency (H	ousing Authority of the	Cherokee Nation) Claim #	12024, Grover Hendri	cksor
FLOORPLAN: Floor	plan			
Girder beam				
1 Remove existing gi	irder beam under center of ho	ouse.		
2 Girder, Wood, Tripl	e, 2"x10" - Tear Out		38.00	LF
3 Match existing size				
4 add girder beam in	same location under house v	where existing one is getting removed.		
5 Girder, Wood, Tripl	e, 2"x10" - Replace		38.00 (41.80)	LF
Includes 10%	waste on material quantity.			
hall				
6 Vinyl Plank Flooring	g, Good - Replace		54.00 (59.40)	SF
Includes 10%	waste on material quantity.			
7 foundation cracks a	at top of doors.must include n	nud,tape,texture.		
8 Drywall, 1/2", Walls	- Replace		90.00 (95.40)	SF
Includes 6% v	waste on material quantity.			
9 Subfloor, Plywood,	CDX, 3/4" - Tear Out		95.00	SF
10 Subfloor, Plywood,	CDX, 3/4" - Replace		95.00 (104.50)	SF
Includes 10%	waste on material quantity.			
11 Underlayment, Plyv	vood, BCX, 3/8" - Replace		95.00 (104.50)	SF
Includes 10%	waste on material quantity.			
<b>□</b> Garage				1
Length: 11'6"	Width: 19'6"	Height: 8' Flat		
Walls: 496.00 SF	Walls-subs: 496.00 SF	Walls-subs-cas-bsbd: 477.92 SF		
Doors: 0.00 SF	Windows: 0.00 SF	Openings: 0.00 SF Missing Walls: 0.00 SF		
Floor: 224.25 SF	Ceiling: 224.25 SF	Perim (F): 62.00 LF Perim (C): 62.00 LF		
12 Drywall, 1/2", Ceilin	gs - Tear Out		224.25	SF
13 new install must inc	lude mud,tape,texture.			
14 Drywall, 1/2", Ceilin	gs - Replace		224.25 (235.46)	SF
Includes 5% v	vaste on material quantity.			
15 Drywall, 1/2", Walls	- Tear Out		156.00	SF
16 must include mud,ta	ape, texture			
17 Drywall, 1/2", Walls	- Replace		156.00 (165.36)	SF
	vaste on material quantity.			
18 Drywall/Plaster Ceili	ing - Paint, 2 Coats		224.25	SF
19 Drywall/Plaster Wall	- Paint, 2 Coats		477.92	SF



escription				Quantity	Per
TIMATE: Emergency (Ho	using Authority of the	Cherokee Nation)	Claim #1	2024, Grover Hendri	ckso
Approved  Laundry Room					
Length: 11'6"  Walls: 297.34 SF  Doors: 0.00 SF  Floor: 81.46 SF	Width: 7'1" Walls-subs: 297.34 SF Windows: 0.00 SF Ceiling: 81.46 SF	Height: 8' Flat Walls-subs-cas-bsbd: Openings: 0.00 SF Perim (F): 37.16 LF	286.50 SF  Missing Walls: 0.00 SF  Perim (C): 37.16 LF		
20 Floor Joist, 2"x8" - Te	ear Out			37.16	LF
21 Floor Joist, 2"x8" - Re				37.16 (40.88)	LF
22 Vinyl Plank Flooring,				81.46 (89.61)	SF
23 Drywall/Plaster Ceilin				81.46	SI
24 Drywall/Plaster Wall -				286.50	SI
25 Subfloor, Plywood, CI 26 T&G	DX, 3/4" - Tear Out			81.46	SI
27 Subfloor, Plywood, CI	DX, 3/4" - Replace vaste on material quantity.			81.46 (89.61)	SI
28 Underlayment, Plywo	od, BCX, 3/8" - Replace vaste on material quantity.			81.46 (89.61)	SF
<b>∵</b> Kitchen					***************************************
Length: 19'	Width: 9'6"	Height: 8' Flat			
Walls: 456.00 SF	Walls-subs: 456.00 SF	Walls-subs-cas-bsbd:	439.38 SF		
<b>Doors:</b> 0.00 SF <b>Floor:</b> 180.50 SF	Windows: 0.00 SF Ceiling: 180.50 SF	<b>Openings:</b> 0.00 SF <b>Perim (F):</b> 57.00 LF	Missing Walls: 0.00 SF Perim (C): 57.00 LF		
29 Floor Joist, 2"x8" - Tea	ar Out			57.00	LF
30 Floor Joist, 2"x8" - Re				57.00 (62.70)	LF
31 Subfloor, Plywood, CD	DX, 3/4" - Tear Out			180.50	SF
32 T&G 33 Subfloor, Plywood, CD	DX, 3/4" - Replace aste on material quantity.			180.50 (198.55)	SF
34 Underlayment, Plywoo				180.50 (198.55)	SF
35 Vinyl Plank Flooring, C				180.50 (198.55)	SF
36 Drywall, 1/2", Ceilings	- Tear Out		annia lavalad	32.00	SF
38 Drywall, 1/2", Ceilings	de mud,tape,texture. and m - Replace ste on material quantity.	ud and tape cracks.after fl	oor is leveled.	32.00 (33.60)	SF
m 12024		Page 5 of 10		07/23	3/20



ription			Quantity	Per
MATE: Emergency (Ho	ousing Authority of the	Cherokee Nation) Claim #120	024, Grover Hendri	ckso
₩ Kitchen(con't)				
39 Drywall/Plaster Ceili	ing - Paint, 2 Coats		180.50	SF
40 Drywall/Plaster Wall			439.38	SF
40 Diywan, Huster Wan	Tuni, 2 cours			
☐ Living Room				
Length: 13'6"	Width: 10'9"	Height: 8' Flat		
Walls: 388.00 SF	Walls-subs: 388.00 SF	Walls-subs-cas-bsbd: 373.84 SF		
Doors: 0.00 SF	Windows: 0.00 SF	Openings: 0.00 SF Missing Walls: 0.00 SF		
		Perim (F): 48.50 LF Perim (C): 48.50 LF		
Floor: 145.13 SF	Ceiling: 145.13 SF	Perim (c): 40.50 LF		
41 Floor Joist, 2"x8" - T	ear Out		48.50	LF
42 Floor Joist, 2"x8" - R			48.50 (53.35)	LF
Includes 10%	waste on material quantity.			
43 Subfloor, Plywood, C	CDX, 3/4" - Tear Out		145.13	SF
44 T&G				
45 Subfloor, Plywood, 0	CDX, 3/4" - Replace		145.13 (159.64)	SF
Includes 10%	waste on material quantity.			
46 Underlayment, Plyw	ood, BCX, 3/8" - Replace		145.13 (159.64)	SF
Includes 10%	waste on material quantity.			
47 Vinyl Plank Flooring	, Good - Replace		145.13 (159.64)	SF
Includes 10%	waste on material quantity.			
48 Drywall, 1/2", Ceiling	gs - Tear Out		145.13	SF
49 Match existing size	when replaced.			
50 new install must incl	lude mud,tape,texture and m	ud,tape cracks after floor is leveled		
51 Drywall, 1/2", Ceiling			145.13 (152.39)	SF
	aste on material quantity.			
52 Drywall/Plaster Ceili			145.13	SF
53 Drywall/Plaster Wall			373.84	SF
☐ Bedroom #2				
Length: 12'11"	Width: 10'	Height: 8' Flat		
Walls: 366.66 SF	Walls-subs: 366.66 SF	Walls-subs-cas-bsbd: 353.30 SF		
Doors: 0.00 SF	Windows: 0.00 SF	Openings: 0.00 SF Missing Walls: 0.00 SF		
Floor: 129.17 SF	Ceiling: 129.17 SF	Perim (F): 45.84 LF Perim (C): 45.84 LF		
54 Floor Joist, 2"x8" - Te			45.84	LF
55 Floor Joist, 2"x8" - R			45.84 (50.42)	LF
	waste on material quantity.		120.17	Cr
56 Subfloor, Plywood, C	DX, 3/4" - Tear Out		129.17	SF
57 T&G			420 47 (442.00)	
58 Subfloor, Plywood, C	CDX, 3/4" - Replace		129.17 (142.09)	SI
m 12024		Page 6 of 10	07/2	3/20



escription	Quantity	Per
	12024, Grover Hendri	ckso
Approved		
Includes 10% waste on material quantity.		
59 Underlayment, Plywood, BCX, 3/8" - Replace	129.17 (142.09)	SF
Includes 10% waste on material quantity.	400 47 (440 00)	
60 Vinyl Plank Flooring, Good - Replace	129.17 (142.09)	SF
Includes 10% waste on material quantity.	51.00	
61 Drywall, 1/2", Ceilings - Tear Out	64.00	SF
62 Must include mud,tape,texture, and mud,tape cracks after floor is leveled.		
63 match existing size.		
64 Drywall, 1/2", Ceilings - Replace	64.00 (67.20)	SF
Includes 5% waste on material quantity.		
65 Drywall/Plaster Ceiling - Paint, 2 Coats	129.17	SF
66 Drywall/Plaster Wall - Paint, 2 Coats	353.30	SF
☐ Bedroom #1		
Length: 11'5" Width: 10' Height: 8' Flat		
Walls: 342.66 SF Walls-subs: 342.66 SF Walls-subs-cas-bsbd: 330.16 SF		
Doors: 0.00 SF Windows: 0.00 SF Openings: 0.00 SF Missing Walls: 0.00 SF		
Floor: 114.17 SF Ceiling: 114.17 SF Perim (F): 42.84 LF Perim (C): 42.84 LF		
67 Floor Joist, 2"x8" - Tear Out	42.84	LF
68 Floor Joist, 2"x8" - Replace	42.84 (47.12)	LF
Includes 10% waste on material quantity.		
69 Subfloor, Plywood, CDX, 3/4" - Tear Out	114.17	SF
70 T&G		
71 Subfloor, Plywood, CDX, 3/4" - Replace	114.17 (125.59)	SF
Includes 10% waste on material quantity.		
72 Underlayment, Plywood, BCX, 3/8" - Replace	114.17 (125.59)	SF
Includes 10% waste on material quantity.		
73 Vinyl Plank Flooring, Good - Replace	114.17 (125.59)	SF
Includes 10% waste on material quantity.		
74 Drywall, 1/2", Ceilings - Tear Out	32.00	SF
75 new install must include mud,tape,texture		
76 mud, tape cracks after floor is leveled.		
77 tear out where mold is and replace with new Match existing size.		
78 Drywall, 1/2", Ceilings - Replace	32.00 (33.60)	SF
Includes 5% waste on material quantity.		
Includes 5% waste on material quantity.  79 Drywall/Plaster Ceiling - Paint, 2 Coats	114.17	SF



ription				Quantity	Per
MATE: Emergency (H	ousing Authority of the	Cherokee Nation)	Claim #120	024, Grover Hendr	ickso
<b>₩</b> Bathroom					
Length: 8'3" Walls: 284.00 SF Doors: 0.00 SF Floor: 62.13 SF	Width: 9'6" Walls-subs: 284.00 SF Windows: 0.00 SF Ceiling: 62.13 SF	Height: 8' Flat Walls-subs-cas-bsbd: Openings: 0.00 SF Perim (F): 35.50 LF	273.64 SF  Missing Walls: 0.00 SF  Perim (C): 35.50 LF		
81 Floor Joist, 2"x8" - 1	Fear Out			35.50	LF
82 Floor Joist, 2"x8" - I Includes 10%	Replace waste on material quantity.			35.50 (39.05)	LF
83 Subfloor, Plywood, 84 T&G	CDX, 3/4" - Tear Out			62.13	SF
85 Subfloor, Plywood, Includes 10%	CDX, 3/4" - Replace waste on material quantity.			62.13 (68.34)	SF
permana	ood, BCX, 3/8" - Replace waste on material quantity.			62.13 (68.34)	SF
87 Vinyl Plank Flooring Includes 10%	, Good - Replace waste on material quantity.			62.13 (68.34)	SF
88 Drywall/Plaster Ceil	ing - Paint, 2 Coats			62.13	SF
89 Drywall/Plaster Wal	- Paint, 2 Coats			273.64	SF
90 Toilet, ADA-Complia	ant, Very Good - Tear Out			1	EA
	ng,supply lines and shut off,to ant, Very Good - Replace	oilet seat.		1	EA
Bedroom #3  Length: 10'6"  Walls: 301.34 SF	Width: 8'4" Walls-subs: 301.34 SF	Height: 8' Flat Walls-subs-cas-bsbd:	290.36 SF		and a second sec
<b>Doors:</b> 0.00 SF <b>Floor:</b> 87.50 SF	Windows: 0.00 SF Ceiling: 87.50 SF	<b>Openings:</b> 0.00 SF <b>Perim (F):</b> 37.66 LF	Missing Walls: 0.00 SF Perim (C): 37.66 LF		
93 Floor Joist, 2"x8" - T	ear Out	***************************************		37.66	LF
94 Floor Joist, 2"x8" - R	eplace waste on material quantity.			37.66 (41.43)	LF
95 Subfloor, Plywood, 0				87.50	SF
97 Subfloor, Plywood, G	CDX, 3/4" - Replace waste on material quantity.			87.50 (96.25)	SF
98 Underlayment, Plyw	ood, BCX, 3/8" - Replace waste on material quantity.			87.50 (96.25)	SF
99 Vinyl Plank Flooring				87.50 (96.25)	SF
100 Drywall/Plaster Ceili				87.50	SF
		Page 8 of 10			3/20



109 Drywall/Plaster Wall - Paint, 2 Coats

scription			Quantity	Per
TIMATE: Emergency (H	ousing Authority of the	Cherokee Nation) Cl	aim #12024, Grover Hend	rickson
Bedroom #3(con't)	ettel mendett satte satte sätere konständ formandet vijangska had dit og eksemplade alle med skam sinder för den s			
101 Drywall/Plaster Wa	ll - Paint, 2 Coats		290.36	SF
☐ Closet				
Length: 6'1" Walls: 122.68 SF	Width: 1'7" Walls-subs: 122.68 SF	Height: 8' Flat Walls-subs-cas-bsbd: 118.18 SF		
Doors: 0.00 SF	Windows: 0.00 SF	Openings: 0.00 SF Missing Walls: 0.00 SF		
Floor: 9.63 SF	Ceiling: 9.63 SF	Perim (F): 15.32 LF Perim (C): 15.32 LF		
102 Floor Joist, 2"x8" - 1	Fear Out		15.32	LF
103 Floor Joist, 2"x8" - I	Replace		15.32 (16.85)	LF
Includes 10%	waste on material quantity.			
104 Subfloor, Plywood,	CDX, 3/4" - Tear Out		9.63	SF
105 T&G				
106 Subfloor, Plywood, Includes 10%	CDX, 3/4" - Replace waste on material quantity.		9.63 (10.59)	SF
	wood, BCX, 3/8" - Replace waste on material quantity.		9.63 (10.59)	SF
108 Drywall/Plaster Ceil			9.63	SF

118.18

SF

# Girder Beam 1-5 \$\_\_\_\_\_\_ Hall 6-11 \$\_\_\_\_\_ Garage 12-19 \$\_\_\_\_\_ Laundry Room 20-28 \$\_\_\_\_\_ Kitchen 29-40 \$\_\_\_\_\_ Living Room 41-53 \$\_\_\_\_\_ Bedroom #2 54-66 \$\_\_\_\_\_ Bedroom #1 67-80 \$\_\_\_\_\_ Bathroom 81-92 \$\_\_\_\_\_ Bedroom #3 93-101\$\_\_\_\_\_

Closet 102-109 \$\_\_\_\_\_

Contractor Signature \_\_\_\_\_

Total- \$\_\_\_\_\_

Date \_\_\_\_\_

Grover Hendrickson