



HACN HOUSING REHAB SITE DIRECTIONS

Name: Bonita French


Telephone: (918)915-1133

Address: 24732 South Hwy 2
Vinita, OK 74301

County: Craig

Year Built: 1962

GPS Coordinates: 36.65977 95.14369 Drive Time: 1 hr 30 mins



Directions: From Cherokee Nation, go to 82 north to Saline at light turn left go to north 435 road turn right then go to west 390 road to 69 north hwy go to 60 to vinita then go thru vinita to hwy 2 will be second house on right.

Darren Choate

Cost Estimator/Inspector

11-30-2021

Date

WorkWrite-Up and Bid Document/By Trade

Bonita French (Emerg Hvac)
24732 S. Hwy 2 Vinita, OK 7-4301
(918) 915-1133

Contractor Name: _____

Contractor Signature: _____

This document must be signed to be a valid bid.

PROJECT TYPE: Emergency Repairs

Bid Due Date: _____

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
HVAC				
1	Area: HVAC	Div.# 12	1 Ea	<input type="text"/>
HVAC Equipment/Replace /Nat Gas Heating 2.5 ton New/Up Flow/13-14 SEER Heating & Cooling Equipment .INCLUDING, COPPER LINES, CONDENSOR COILS, EVAP. COILS. Thermostat .And all necessary electrical wiring Make all repairs needed for installation.				
2	Area: KITCHEN	Div.# 12.N	1 Ea	<input type="text"/>
Wall Heater/Disconnect/Remove unvented space heater/seal gas line in wall or crawlspace/test gas line for leaks/repair surface to match existng. Remove wall heater in the kitchen area.				
Plumbing				
3	Area: PLUMBING	Div.# 11.A	45 LF	<input type="text"/>
Gas Lines/Replace/ Replace all gas lines in and under the structure to all existing gas appliances. Work shall include approved shutoff valves and Flex supply lines to all appliances. Replace all gas lines, run the new gas line to new furnace				

<i>Trade</i>	<i>Work Description / Comments</i>	<i>Gen. Spec.</i>	<i>Qty Unit</i>	<i>Item Bld</i>
<u>Plumbing</u>				
4	Area: PLUMBING	Div.# 11.A	1 Ea	<input type="text"/>
Pressure Test Gas Line/Cap/Entire Structure. Cap all gas lines in and under structure. All gas lines not connected to code-approved appliances and heating sources.				
<u>Sheetmetal & Gutters</u>				
5	Area: HVAC	Div.# 5.J	8 LF	<input type="text"/>
Furnace Vent Pipe/Double-Wall/3"/Replace. Replace 3" gas furnace double-wall vent pipe. The existing furnace has Pvc pipe.				
All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement.				Total: <input type="text"/>