

HACN HOUSING REHAB SITE DIRECTIONS

Participant:	Samuel Boli	n		
Telephone:	Home:	(918) 773-2726	*******	
	Business:			
	Mobile			
Address:	PO Box 613 Vian OK 74	104440 S 4510 Rd 962		
County: §	Sequoyah	Year Built:	1968	
GPS Coordin	nates: <u>35.5</u>	0094,-94.99119		



Directions: From Cherokee Nation, Hwy 62 to traffic circle, south to McQuiks, turn south to 64. Rt at 4 way in Vian, West toS 4510 Rd first house on left. White house

Michael Knapp	07/21/2025	
Cost Estimator/Inspector	Date	

Revised: 1/2017



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

				Quantity	Per
MATE: Emergency (H	Housing Authority of the	Cherokee Nation)	Claim #	‡12287, Samuel	Bolin
EXTERIOR PLAN: I	exterior Plan				
Exterior Plan	7				
Exterior: 171.00 SF					
Subtractions: 0.00	SF				
1 Porch post need to	o be 4"x4"x16'				
2 Post, In Concrete,	Pressure Treated, 4"x4"x6' - Rep	place		6 (6.30)	EA .
Includes 5%	waste on material quantity.				
3 Deck Joists, Treate	ed Pine, 2"x6", 16" O.C Replace	e		171.00 (179.55)	SF_
	waste on material quantity.				
-	Pine, 5/4"x6" - Replace			171.00 (179.55)	SF _
	waste on material quantity.			27.00 (27.27)	
	iling, Complete, Pressure Treate	ed 2" x 6"		37.00 (38.85)	LF_
Includes 5%	waste on material quantity.				
	. D. L.			20	EA
6 Joist Hanger, 2"x6				20	EA _
6 Joist Hanger, 2"x6 7 Pressure treated S	tairs			20 5.00	EA _
6 Joist Hanger, 2"x67 Pressure treated S8 Stairs, Hardwood,	tairs 4', No Landing - Replace				
6 Joist Hanger, 2"x6 7 Pressure treated S	tairs 4', No Landing - Replace				
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, COORPLAN: Floor Bathroom	tairs 4', No Landing - Replace r plan				
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, COORPLAN: Floor Bathroom Length: 8'	tairs 4', No Landing - Replace rplan Width: 10'	Height: 8' Flat			
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, COORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF	Walls-subs-cas-bsbd: 277.50 SF	0.00.55		
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, **LOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls:			
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, COORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF	Walls-subs-cas-bsbd: 277.50 SF			
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, COORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls:		5.00	
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, ELOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls:			LF_
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, ELOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity.	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls:		5.00	LF_
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, **LOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109 10 Linoleum Sheet Floor	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity. poring, Good - Replace	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls: Perim (F): 36.00 LF Perim (C): 36.0		5.00	LF
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, ELOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109 10 Linoleum Sheet Floor Includes 209	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity. poring, Good - Replace 6 waste on material quantity ca	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls: Perim (F): 36.00 LF Perim (C): 36.0		5.00	LF
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, **LOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109 10 Linoleum Sheet Floor	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity. pooring, Good - Replace 6 waste on material quantity can	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls: Perim (F): 36.00 LF Perim (C): 36.0		5.00 80.00 (88.00) 80.00 (96.00)	LFSF
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, ELOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109 10 Linoleum Sheet Floor Includes 209 11 Toilet Flange - Rer	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity. poring, Good - Replace 6 waste on material quantity canove	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls: Perim (F): 36.00 LF Perim (C): 36.0		5.00 80.00 (88.00) 80.00 (96.00)	LFSFEA
6 Joist Hanger, 2"x6 7 Pressure treated S 8 Stairs, Hardwood, **LOORPLAN: Floor Bathroom Length: 8' Walls: 288.00 SF Doors: 0.00 SF Floor: 80.00 SF 9 Subfloor, Plywood Includes 109 10 Linoleum Sheet Floor Includes 209 11 Toilet Flange - Rer 12 Toilet Flange - Rer	tairs 4', No Landing - Replace rplan Width: 10' Walls-subs: 288.00 SF Windows: 0.00 SF Ceiling: 80.00 SF , BCX, 1-1/8" - Replace 6 waste on material quantity. poring, Good - Replace 6 waste on material quantity can hove place 1/2 Ton	Walls-subs-cas-bsbd: 277.50 SF Openings: 0.00 SF Missing Walls: Perim (F): 36.00 LF Perim (C): 36.0		80.00 (88.00) 80.00 (96.00)	SF_SF_EA_EA_



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

Description	C	Quantity	Per
ESTIMATE: Emergency (Housing Authority of the Cherokee Nation) Approved	Claim #1	2287, Samuel	Bolin
Roof, Roof 2			
Roof area: 1,447.84 SF Squares: 14.5 SQ Soffit: 295.54 SF Eaves: 139.00 LF Ridge: 30.50 LF			
GUTTER ITEMS			
DEBRIS REMOVAL			
16 New install- no existing gutter			
17 Gutter & Guard, One-Piece, Seamless - Replace		139.00 (145.95)	LF _
Includes 5% waste on material quantity.			
18 Downspout Splash Block, Vinyl/Plastic - Replace		7	EA _
19 Downspout, Aluminum, 2"x3" - Replace Includes 5% waste on material quantity.		63.00 (66.15)	LF
	_	Total	·
		TOtal Eate:	
	Contractor Signature:		