

NELAC NY 11769
NRPP 103216 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested:

Cherokee Nation of Oklahoma - Shaun West
PO BOX 948
Tahlequah OK 74465

Cherokee Heritage Center
Not Indicated 4300613 4300611
Tahlequah OK 74464

Log Number	Device Number	Test Exposure Duration:		Area Tested		Result pCi/L
2806468	4300613	11/20/2020 2:00 pm	11/24/2020 10:09 am	Bldg. HC Basement Room Finance		12.1
2806469	4300614	11/20/2020 2:05 pm	11/24/2020 10:12 am	Bldg. HC Basement Room Barb's Office		12.6
2806470	4300612	11/20/2020 2:10 pm	11/24/2020 10:15 am	Bldg. HC Basement Room Curator		11.9
2806471	4300615	11/20/2020 2:15 pm	11/24/2020 10:20 am	Bldg. HC First Floor Room Gift Shop		11.2
2806472	4300611	11/20/2020 2:15 pm	11/24/2020 10:08 am	Bldg. HC First Floor Room Genealogy		9.1

Comment: Client declined lab's request for a property test address. Cherokee Nation of Oklahoma was e-mailed a copy of this report. A copy of this report was emailed to swest@cherokee.org.

Test Performed By: Placed: Shaun West Retrieved: Shaun West

Distributed by: Cherokee Nation of Oklahoma

Date Received: 11/25/2020 Date Logged: 11/25/2020 Date Analyzed: 11/26/2020 Date Reported: 11/27/2020

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The uncertainty of this radon measurement is $\sim \pm 10\%$. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.