## WorkWrite-Up and Bid Document/By Trade

	(918) 341-2034	604 S Choctaw Claremore, OK 7-4017	Eliza Hamilton
		7-4017	
This document must be signed to be a valid bid.	Contractor Signature:		Contractor Name:

	PROJECT TYPE: Rehabilitation	Rehabilitation	Bid Due Date:	
Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry				
1 Area: BEDROOM #1	DOM #1	<i>Div.</i> #6.M.2	10 LF	
Level /Floor: Place on 18" x 18"x 12" o	Level /Floor: Place Triple 2"x 8" girder beam beneath floor joist, use Girder Jacks placed on 18" x 18"x 12" concrete piers placed 8' O/C to lift and hold beam.	joist, use Girder Jacks placed ld beam.		
2 Area: BEDROOM #2	OOM #2	Div.#6.M.2	12 LF	
Level /Floor: Place on 18" x 18"x 12" c	Level /Floor: Place Triple 2"x 8" girder beam beneath floor joist, use Girder Jacks placed on 18" x 18"x 12" concrete piers placed 8' O/C to lift and hold beam.	joist, use Girder Jacks placed ld beam.		
3 Area: LIVING ROOM #1	ROOM #1	Div.#6.M.2	560 LF	
Level /Floor: Place on 18" x 18"x 12" c	Level /Floor: Place Triple 2"x 8" girder beam beneath floor joist, use Girder Jacks placed on 18" x 18"x 12" concrete piers placed 8' O/C to lift and hold beam.	joist, use Girder Jacks placed ld beam.		
4 Area: KITCHEN	EZ	Div.#6.0.2	15 LF	
Base Cabinets/Ins	Base Cabinets/Install/Oak. Install new base cabinets/pre-finished oak.	ished oak.		
5 Area: KITCHEN	EZ	Div.#6.0.4.	15 LF	
Countertop/New/P	Countertop/New/Post Form Top. Install new countertop and backsplash.	backsplash.		

Trade Work Description / Comments	ts Gen. Spec.	Qty Unit	Item Bid
Carpentry			
6 Area: EXTERIOR	Div.# 8.A.	1 Ea	
Door/Exterior/6-Panel Steel/Pre-Hung/Replace. Replace exterior entrance door with new pre-hung-steel six panel door. Work shall include paint-both sides, lockset, deadbolt & peephole.	e exterior entrance door with new- both sides, lockset, deadbolt &		
back entry			
7 Area: EXTERIOR	Div.# 8.A.	1 Ea	
Door/Exterior/Half-Glass/Pre-Hung Steel/Replace. Replace exterior entrance door with new pre-hung-steel two panel with 1/2 glass. Work shall include paint-both sides, lockset, deadbolt & peephole.	lace exterior entrance door with include paint-both sides, lockset,		
front entry			
8 Area: BATHROOM #1	Div.# 8.D.2.	1 Ea	1
Door/Rehang interior door. Remove casing, replumb door & reinstall casing.	oor & reinstall casing.		
9 Area: KITCHEN	Div.# 10.G	1 Ea	
Fire Extinguisher/Install. Install new fire extinguisher.			
10 Area: EXTERIOR	Div.# 6.FF	300 SF	
Flooring/Porch Floor/Repair. Repair porch floor. See comments			
remove and replace existing 5/4" terated decking			
11 Area: EXTERIOR	<i>Div.</i> # 8.B	2 Ea	1
Storm Door/Vinyl Clad. Replace storm/screen door with new Heavy Duty 1 1/4" white vinyl clad storm door.	n new Heavy Duty 1 1/4" white		Г
12 Area: LIVING ROOM #1	Div.# 6.D.	32 SF	
Subfloor/Replace/Small Area/3/4" Plywood. Replace subfloor with new 3/4" plywood.	ubfloor with new 3/4" plywood.		

Trade Work Description / Comments	Gen. Spec.	Otv Unit	Item Rid
Carpentry			
13 Area: KITCHEN	Div.# 6.0.2	20 LF	
Wall Hung Cabinets/Pre-Finished Oak. Install new wall hung cabinets (pre-finished oak).	re-finished oak).		
14 Area: EXTERIOR	Div.# 8.G	12 Ea	
Window/Replace/Vinyl Thermopane/Low-E. Replace window with new Solid Vinyl window/single hung. Use Am. Craftsman Series 2160-Vinyl or written approved equal. Any damage done to ext or int surfaces shall be repaired by the installer.	olid Vinyl proved equal.		
Electrical			
15 Area: INTERIOR	<i>Div.</i> # 13.D.	1 Ea	
Light Fixture, Circuit & Switch/Porch/Ceiling Mounted. Install new exterior porch light, circuit wiring with switch and cover.	r porch light,		
16 Area: BEDROOM #1	Div.# 13.D.	4 Ea	
Outlet/110v/Repair 110 outlet/See comments.			
replace all outlets and light switch -currently only 1 outlet working			
17 Area: INTERIOR	Div.# 13.D.	3 Ea	
Smoke Detector/Battery Operated/Install new smoke detector, battery operated (10 year lithium battery). All bedrooms and hallways adjacent to bedrooms. Use Firex #4015 or written approved equal.	erated (10 year irex #4015 or		
Bedrooms and livingroom			
Flooring			

Trade Work Description / Commonts	0	2. 2.1
Flooring		
18 Area: INTERIOR Div.# 9.M	75 SY	
Carpet & Pad/Nylon/25 oz./Install new carpet (25 oz. face weight/nylon with 5 year wear and stain warranty) and pad (7/16"- 6 lb.).		
2 living areas, 2 bedrooms, hallway		
HVAC		
19 Area: HVAC Div.# 12.M.	1 Ea	
HVAC System/Service. Service complete HVAC system. INCLUDES; Freon Charge, Capacitors, Cleaning Coils, and Repair of line leaks See General Specifications.		
Plumbing		
20 Area: BATHROOM #1 Div.# 16.C.	1 Ea	
Commode/High Rise/Replace existing commode with new high rise commode with two (2) grab bars. Work shall include new shutoff, supply line and wax ring. Examine condition of the flange and report if damaged. Consult owner for location of grab bars.		
21 Area: BATHROOM #1 Div.# 11.A	1 Ea	
P-Trap/Replace. Replace P trap and drain lines at sink.		
22 <i>Area</i> : KITCHEN <i>Div.</i> # 11.A	1Ea	
Sink & Faucet/Kitchen. Install new stainless steel kitchen sink (33" x 22" x 7") & Faucet (Use Delta single-handle model100-WF or written approved equal). Work shall include new drain lines, trap and shutoffs (2).		
Site Work		

Trade Work Description / Comments Gen. Spec.	Qty Unit	Item Bid
Site Work		
23 Area: ENTIRE STRUCTURE Div.# 2.Q	900 SF	
Pests/Treat Structure. Treat structure for pests, including spiders, ants, and cockroaches. Use a Oklahoma State Licensed Applacator. Provide treatment information at completion to the Home Owner and Housing Rehab Inspector.		
×		
24 Area: ENTIRE STRUCTURE  Div.# 2.Q	1200 SF	
Termites-Wood Destroying Insects/Treat Structure. Treat structure for wood destroying insects. Use state licensed applicator.		
Thermal Protection		
25 Area: ATTIC Div.# 14	900 SF	
Insulation/Add/Attic/R-19. Add R-19 Cellulose in attic. Entire attic over air conditioned & heated spaces.		
All construction shall be in accordance with local codes, manufacturers' recommended		

attached Asbestos Sampling Report for location and testing of Planned Work Activities. Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See compliance with the more stringent requirement. Contractor awarded the job will be responsible Based Paint requirements when applicable. Conflicts between requirements will be resolved by for conducting safe work practices that comply with OSHA Construction Standards for Asbestos installation procedures, good quality workmanship practices, General Specifications and Leadice, manuacturers recommended

CARDRET	(zarage	Enclosed	Storage 12X16	
Front Porch	Living Room	Kitchen 7 x 12	CItilty Room Pox 8	GOY Chockow
		BAth 5X7	J. Bek	
	Bodroom 2	Bedroom 1	nek Porch	CITTICINOIC

## Housing Rehab Site Directions

1	. 1	11	10
. V	. 1	11	11

Eliza Hamilton

Telephone:

918-341-2034

Address:

604 South Choctaw Ave Claremore

GPS:

DRIVING TIME Directions:

From Cherokee Nation:

Take Hwy 62 West to Muskegee

Take Hwy 69 North to Pryor

Take Hwy 20 West 26 Mile to Claremore

Take Hwy 20 West 26 Mile to Claremore

Torn Left on Lynn Riggs Rd.

Torn Left on SH 88

Go 40 yards Turn Left on SH 88

Go 5/10 mile Turn Right on Choctaw

Go 5/10 mile Ilouse on Left.

Lov. d Tackett

ŀ

7/8/14

Date