

WorkWrite-Up and Bid Document/By Trade

Asia Booker

206 east Scott Sallisaw, OK 7-4955
 (918) 774-6751

Contractor Name:

Contractor Signature:

This document must be signed to be a valid bid.


PROJECT TYPE: Emergency Repairs **Bid Due Date:**

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry				
1	Area: KITCHEN Base Cabinet/Remove. Remove base cabinet(s) at specified location(s). remove and reinstall cabinets and countertops	Div.# 6.O..2	10 LF	<input type="text"/>
2	Area: BEDROOM #2 Floor System/Replace. Replace entire floor system, include rim joists, floor joist, mudseal, 3/4" T&G subflooring.	Div.# 6.D.	144 SF	<input type="text"/>
3	Area: INTERIOR Floor System/Replace. Replace entire floor system, include rim joists, floor joist, mudseal, 3/4" T&G subflooring. living , dining , kitchen and hallway	Div.# 6.D.	500 SF	<input type="text"/>
4	Area: CRAWLSPACE Girder Beam/Triple 2" x 6"/Install. Install triple 2" x 6" girder beam. 2 25 ft in living and 1 12 ft in bedroom	Div.# 6.FF.	62 LF	<input type="text"/>

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
-------	-----------------------------	------------	----------	----------

All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement.

Total:



HACN HOUSING REHAB SITE DIRECTIONS

Name: Asia Booker

Telephone: (918)774-6751

Address: 206 East Scott

Sallisaw, OK 74455

County: Sequoyah

Year Built: 1979 1940's

GPS Coordinates: 35.7376 - 94.7335 **Drive Time:** 1 hr

Directions: From Cherokee Nation,
Take Hwy 82 to Vian
Take Hwy 64 to Sallisaw
Take Hwy 59 south to Ruth st
turn left , go past Wal-mart 3/4 mile to Chestnut
turn left , go to Scott : house on left

David Tackett

7-21-22

Cost Estimator/Inspector

Date