

HACN HOUSING REHAB SITE DIRECTIONS

Name: <u>Douglas Hawkins</u> Telephone: <u>(918)650-2423</u>

Address:

8567 E 128 St S

Muskogee, OK 74403

County: Muskogee

Year Built: 1990

GPS Coordinates: 35.57379,-95.23247 Drive Time: 1 Hr



Directions: From Cherokee Nation, Continue to US-62 W

1 min (0.2 mi) Head east 404 ft Turn right toward US-62 W 449 ft Turn left toward US-62 W 69 ft Continue on US-62 W. Take US-64 E to E 133rd St S/E100 in Muskogee County 43 min (39.9 mi) Turn right onto US-62 W 0.3 mi Slight right toward US-62 W 335 ft Merge onto US-62 W 20.6 mi Use the right lane to merge onto OK-165 S/OK-351 via the ramp to Ft Smith 3.2 mi Take the OK-165 W/Peak Blvd exit toward US-64 0.3 mi Continue onto OK-165 W/E Peak Blvd 4.0 mi Turn left onto the ramp to Ft. Smith 0.3 mi Continue onto US-64 E 11.1 mi Continue on E 133rd St S. Drive to E 123rd St S/E 128th St S 8 min (5.0 mi) Turn left onto E 133rd St S/E100 Continue to follow E 133rd St S 4.4 mi Turn left onto 85th St 0.5 mi Turn right onto E 123rd St S/E 128th St S

Destination will be on the right 492 ft 8567 E 128th St S Muskogee, OK 74403

Rodney Carman (918) 506-9858

9/3/2024

Cost Estimator/Inspector

Date

WorkWrite-Up and Bid Document/By Trade

Douglas Hawkins 3567 E 128 Sst S Muskogee, OK 7	Contractor Name: 7-4403 Contractor Signature:			
0-0) 000 1-10	This	s document must be s	This document must be signed to be a valid bid.	
	PROJECT TYPE: Emergency Repairs	airs	Bid Due Date:	
Trade Work Descripti	Work Description / Comments G	Gen. Spec.	Qty Unit	Item Bid
Carpentry				
Area: BATHROOM #2		Div.#16.B.2	1Ea	
ססר Opening/Widen/Interior/Widen interior door to 36" opening/Install new door/ pre- יוחק. Work shall include new door, framing, lockset, floor transition, paint and trim.	ior door to 36" opening/Install new do	oor/ pre- trim.		
Area: EXTERIOR		Div.#6.C.	28 SF	
Exterior Wall/Repair. Replace exterior wall Sheathing 1/2" OSB (framing only).	III Sheathing 1/2" OSB (framing only))		
Natch existing siding North side of dwelling where siding is bad	ng where siding is bad			
Area: BATHROOM #2		Div.#11.A.3	1Ea	
ਤੇrab Bar/Stainless Steel. Install new stainless steel grab bar. Owner shall determine ocation.	nless steel grab bar. Owner shall dete	ermine		
Area: BATHROOM #2		Div.#6.D	85 SF	
Subfloor/Repair. Repair subfloor/See comments.	nments.			
nstall hardi board for underlayment to match existing hardiboard installed under toilet	atch existing hardiboard installed under	er toilet		

Trade	Work Description / Comments	omments	Gen. Spec.	Qty Unit	Item Bid	3id
lumbing						
10 Area: BATHROOM #2	M #2		Div.# 16.C.	1Ea		
Shower/Handicap/Pre- cold down shower sea	Fab/Install new 32" x 60"; t, and pressure balanced;	Shower/Handicap/Pre-Fab/Install new 32" x 60" x 74" /Pre-fab 3 piece with grab bars, rold down shower seat, and pressure balanced shower valve with glide bar. Includes all	grab bars, r. Includes all		Г	
All construction sha	Il be in accordance with	All construction shall be in accordance with local codes, manufacturers' recommended	ers' recommended	T	otal:	
installation procedu	res, good quality workm	installation procedures, good quality workmanship practices, General Specifications and Lead-	al Specifications and	Lead-	i ki ve v ga	(Included the control of the control
Based Paint requirer	nents when applicable.	Based Paint requirements when applicable. Conflicts between requirements will be resolved	rements will be resol	ved by	To the Proposition of the Propos	Name of Street Street

compliance with the more stringent requirement.