

Scope of Work for Chair upholstery/Repair

We will be sending out up to 200 chairs for repair. This is an approximate number. These will not all require repair at the same time and will not necessarily need all units repaired on every chair. The exact material listed below must be used. We would like to have a vendor within a 30 mile radius to ensure a quick turnaround time. This price must include pickup and delivery and material.

Repair Units Possible:

- Outer back
- Inside back
- Seat
- Seat border

Material Required:

Color - Black

Hi-flex backing

UV Stabilized 500hrs. QUV-B

weatherometer 1500 hrs.

Cold crack -10F

Abrasion 500,000 Double rubs

mildew resistant

antimicrobial/antibacterial

oil and sulfide stain resistant

