

SCOPE OF WORK

Fire Sprinkler Systems update requirements 2013

Cherokee Casino
31501 HWY 75
Ramona Okla. 74061

Engage **VENDOR** to supply all labor and materials to perform correction of deficiencies in accordance with **NFPA #25. NFPA #13 National Fire Alarm Code**

To match or exceed materials and labor required to correct in regards to report Firetrol Protection Systems dated 08/27/2013.

1: The following **NFPA #25** Fire Protection Sprinkler Wet System listing requiring removal and replacement of nonfunctioning sprinkler heads caused by the corrosion or accumulation of dust or latex paint residue within location of the Ramona HWY 75 Structure Non Public access and public viewing area. Install as required by State Codes within allowable spacing or provide extended coverage sprinkler were noted requirements NFPA 13 2012 edition.

2: The following **NFPA #25 /NFPA #13** Fire Protection Sprinkler Wet System listing requiring removal and replacement of nonfunctioning sprinkler heads caused by the corrosion or accumulation of dust or latex paint residue within location of the Main Casino Gaming ceiling area.

3: The following **NFPA #25** Fire Protection Sprinkler Wet System listing requiring replacement or installation of all damaged or missing semi recess metal escutcheons throughout the Ramona system area.

4: The following **NFPA #25** Fire Protection Sprinkler Cooler and Freezer storage warehouse system recharge and re-test to meet code requirements of below 0 degrees Ante-Freeze percent by standards. Replace line system test port and backflow piping to code requirements using proper materials.

5: The following **NFPA #25** Fire Protection Ramona's Sprinkler Riser Room 1st floor piping correction of the design installation metal vertical 4 in check valve and housing. Refer to NFPA 13 on install ball drip connection refer to notation 08272013

VENDOR will use only approved methods and materials to complete this task while all work to be performed during approved normal business hours.

Ramona Casino HWY 75 Okla. 74061 2013