Fire Sprinkler Systems Hard Rock Hotel and Casino 777 W Cherokee St Catoosa, OK 74015

Engage **VENDOR** to supply all labor and materials to perform deficiency repairs of the fire sprinkler systems located at the facility. This inspection will be in accordance with **OAC 310:205-3-7**, **NFPA #13** and the **Local Authority having Jurisdiction**. **VENDOR** will use only approved methods and materials to complete this work. All work will be performed during approved normal business hours.

VENDOR will perform the work indicated below:

Fire Sprinkler Systems

Cherokee Tower

- 1. Replace residential fire sprinkler in commercial application 7th floor north end of hall
- 2. Replace damaged fire sprinkler in room 710
- 3. Replace residential fire sprinkler in commercial application 6^{th} floor south end of hall
- 4. Replace loaded fire sprinkler 3rd floor security surveillance
- 5. Add additional coverage in 3rd floor IT surveillance server room
- 6. Add additional coverage in 3rd floor surveillance center entrance
- 7. Repair or replace flow switch 3rd floor IT offices above ceiling
- 8. Repair or replace tamper switch IT offices above ceiling
- 9. Repair Damaged fire sprinkler Executive offices senior marketing director
- 10. Add additional coverage to H.R. vacant office south end
- 11. Replace or clean painter fire sprinkler Hotel room 328
- 12. Re place (2) discolored fire sprinklers 2nd floor backhouse banquets electrical room
- 13. Add coverage to 2nd floor food and beverage office mechanical room
- 14. Reinstall (3) improperly installed fire sprinklers Riffs bar
- 15. Correct (3) Improperly installed fire sprinklers West of men's room
- 16. Correct improperly installed fire sprinkler Riffs stage
- 17. Correct Improperly installed fire sprinkler West of Riffs maroon soffit
- 18. Correct Improper coverage Outside Gary's office in hallway
- 19. Correct improper installation fire sprinkler Player's club office
- 20. Repair Damaged fire sprinkler outside employee entrance security door
- 21. Repair or replace Damaged fire sprinkler In front of vault cashier

Hard Rock Tower

- 1. Replace painted fire sprinkler Outside McGills employee elevator
- 2. Replaced corroded fire sprinkler McGills Kitchen
- 3. Fix improperly installed sprinkler in McGills above hostess station

- 4. Add additional sprinkler coverage in 17th Floor behind false wall by ice machine
- 5. 2nd floor Room service office
- 6. Clean or replace (20) Loaded fire sprinklers and missing escutcheon in Toby Keith's kitchen
- 7. Clean or replace 2) Loaded fire sprinklers in Toby Keith's under balcony seating
- 8. Replace damaged fire sprinkler in Paint storage
- 9. Replace damaged fire sprinkler in Banquet hall back of house south emergency exit
- 10. Replace damaged fire sprinkler in Banquet hall back of house by ice machine
- 11. Fix improperly installed fire sprinkler
- 12. Clean or replace (4) loaded fire sprinklers in Basement laundry

Suites Tower(Casino 3)

- 1. Replace (2) painted cover plates in Main entrance to Casino 3
- 2. Add additional fire sprinkler coverage to closet west of Flip side
- 3. Replace missing cover plate 1st floor Men's restroom
- 4. Replace missing cover plate Pedestrian bridge
- 5. Add additional fire sprinkler coverage to pedestrian bridge electrical/storage room
- 6. Add additional fire sprinkler coverage to C3-207
- 7. Replace or Repair damaged dry pendent sprinkler in Replay beer cooler

Casino 4(Sprung) Wet Systesm:

- 1. Add additional fire sprinkler coverage to Entrance to Men's restroom
- 2. Add additional fire sprinkler coverage to Entrance to Women's restroom
- 3. Clean or replace loaded fire sprinkler in Bottleneck above ice machine
- 4. Clean or replace (6) loaded fire sprinkler in Bottleneck
- 5. Add head box in riser room

Fire Pumps

Hard Rock Tower

Fire pump would not transfer.