

Map data ©2023 Google 2 mi

Tahlequah Oklahoma 74464

- 1. Head south on S Muskogee Ave toward W Shawnee St
 - 1 Pass by BancFirst (on the right in 0.2 mi)

 At the traffic circle, take the 2nd exit onto State Hwy 82

13.7 mi

3. Turn right onto W Cookson Bend Rd

1.7 mi

4.1 mi

4. Turn left onto S 528 Rd/Singapore Rd

Destination will be on the left

384 ft

32381 S 528 Rd Cookson, OK 74427



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

cription	Quantity	Per
IMATE: Rehab (Housing Authority of the Cherokee Nation)	Claim #10646, Roy	Miller
Approved	发展,是一种一种。 及一种产品	
FLOORPLAN: Floorplan		
Cooktop & Oven		
1 Cooktop, Countertop, Electric Very Good - Remove	1	EA
2 Cooktop, Countertop, Electric Very Good - Replace	1	EA
3 Oven, Built-In, Electric Very Good - Replace	1	EA
4 Oven, Built-In, Electric Very Good - Remove	1	EA
5 Dumpster 20 Yard	1	EA
Windows		
6 Window, Double Hung, Vinyl Clad Medium - Remove	16	EA
7 Window, Double Hung, Vinyl Clad Medium - Replace Ramp	16	EA
8 Wheelchair Ramp, Medium - Replace	1	EA
9 Sidewalk, per SF - Replace Deck	80.00	SF
DECK FRAMING ITEMS		
10 Deck Girder Treated Pine 2"x6" - Tear Out	12.00	LF
11 Deck Girder Treated Pine 2"x6" - Replace [Includes 5% waste on material quantity.	12.00 (12.60)	LF
12 Deck Joists (SF), Treated Pine 2"x6", 16" o.c Tear Out	96.00	SF
13 Deck Joists (SF), Treated Pine 2"x6", 16" o.c Replace Includes 5% waste on material quantity.	96.00 (100.80)	SF
14 Ledger Board, Treated Pine 2"x8" - Tear Out	12.00	LF
15 Ledger Board, Treated Pine 2"x8" - Replace Includes 5% waste on material quantity.	12.00 (12.60)	LF
16 Decking, Treated Pine, 5/4" thick - Tear Out	96.00	SF
17 Decking, Treated Pine, 5/4" thick - Replace [Includes 5% waste on material quantity.	96.00 (100.80)	SF
18 Deck Railing Complete, Pressure Treated - Tear Out	24.00	LF
19 Deck Railing Complete, Pressure Treated - Replace Includes 5% waste on material quantity.	24.00 (25.20)	LF
DEBRIS REMOVAL		

L' Master Bathroom	
Length: 11'9"	Width: 13'4" Height: 8' Flat
Walls: 401.34 SF	Walls-subs: 381.34 SF Walls-subs-cas-bsbd: 289.91 SF
Doors: 20.00 SF	Windows: 0.00 SF Openings: 0.00 SF Missing Walls: 0.00 SF
Floor: 156 67 SF	Ceiling: 156.67 SE Perim (F): 46.58 IF Perim (C): 50.16 IF

20 Shower Stall, Fiberglass Very Good - Remove

EA



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

Includes 6% waste on material quantity.

scription		Quantity	Per
TIMATE: Rehab (Housing Authority of the Cherokee Nation) Approved	Claim	#10646, Roy	Miller
☐ Master Bathroom(con't)			
21 Shower Stall, Fiberglass Very Good - Replace Install low curb handicap shower.		1	EA
22 Faucet & Showerhead Single Valve, Good - Remove		1	EA
23 Grab Bar, Handicap, per LF - Replace [Install four 2' grab bars.		8.00	LF
24 Faucet & Showerhead Single Valve, Good - Replace		1	EA
25 Toilet, 1 Piece, Very Good - Remove		1	EA
26 Toilet, Handicap Very Good - Replace		1	EA
27 Drywall, Ceiling 1/2", Taped - Remove		156.67	SF
28 Drywall, Ceiling 1/2", Taped - Replace Includes 5% waste on material quantity.		156.67 (164.50)	SF
29 Texture, Ceiling, Popcorn, Light - Replace		156.67	SF
30 Drywall/Plaster Ceiling - Prime & Paint		156.67	SF
31 Carpet & Pad, Good - Remove		100.28	SF
32 Linoleum, Sheet Very Good - Replace [Includes 10% waste on material quantity.]		11.14 (12.25)	SY
33 Insulation, Ceiling, Batt, Faced 6", R-19 - Remove		156.67	SF
34 Insulation, Ceiling, Batt, Faced 6", R-19 - Replace		156.67	SF
□ Laundry Room			
Length: 5' Width: 10'2" Height: 8' Flat Walls: 242.66 SF Walls-subs: 242.66 SF Walls-subs-cas-bsbd: 200.64 SF Doors: 0.00 SF Windows: 0.00 SF Openings: 0.00 SF Missing Walls: 0.00 SF			
Floor: 50.83 SF Ceiling: 50.83 SF Perim (F): 30.34 LF Perim (C): 30.34 LF			
35 Drywall, Wall 1/2" - Remove		242.66	SF
36 Drywall, Wall 1/2" - Replace		242.66 (257.22)	SF



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

cription	Quantity	Per
Approved Approved	Claim #10646, Roy I	Miller
☐ Dining Room		
Length: 11' Width: 13'1" Height: 8' Flat Walls: 385.34 SF Walls-subs: 345.34 SF Walls-subs-cas-bsbd: 327.39 SF Doors: 40.00 SF Windows: 0.00 SF Openings: 0.00 SF Missing Walls: 0.00 SF Floor: 143.92 SF Perim (F): 41.58 LF Perim (C): 48.16 LF		
41 Door, Patio, Sliding, Aluminum, 6'-8" 2 Panel, 6' - Remove	1	EA
42 Door, Patio, French, Steel 6'-0" x 6'-8" - Replace	1	EA
43 Lockset, Exterior Very Good - Replace	1	EA
44 Door, Patio, French, Single - Prime & Paint Prime and paint both sides of both doors being installed.	1	EA
45 Carpet & Pad, Very Good - Remove	143.92	SF
46 Carpet & Pad, Very Good - Replace Includes 22.29% waste on material quantity calculated by Rollout Calculator.	143.92 (176.00)	SF
47 Subfloor Plywood, 3/4" - Remove	32.00	SF
48 Subfloor Plywood, 3/4" - Replace Includes 10% waste on material quantity.	32.00 (35.20)	SF
☐ Living Room		
Length: 15'10" Width: 26'8" Height: 8' Flat Walls: 680.01 SF Walls-subs-cas-bsbd: 655.21 SF Doors: 0.00 SF Windows: 0.00 SF Openings: 0.00 SF Missing Walls: 0.00 SF Floor: 401.99 SF Perim (F): 84.99 LF Perim (C): 84.99 LF	And and an extension of the	
49 Carpet & Pad, Very Good - Remove	401.99	SF
50 Carpet & Pad, Very Good - Replace Includes 10.29% waste on material quantity calculated by Rollout Calculator.	401.99 (443.35)	SF
51 Drywall, Ceiling 1/2", Taped - Remove	401.99	SF
52 Drywall, Ceiling 1/2", Taped - Replace Includes 5% waste on material quantity.	401.99 (422.09)	SF
53 Texture, Ceiling, Popcorn, Light - Replace	401.99	SF
54 Drywall/Plaster Ceiling - Prime & Paint	401.99	SF
55 Insulation, Ceiling, Batt, Faced 6", R-19 - Remove	401.99	SF
56 Insulation, Ceiling, Batt, Faced 6", R-19 - Replace	401.99	SF

Total:_