

HACN HOUSING REHAB SITE DIRECTIONS

Name: Celia Logan

Telephone: (479) 285-4885

Address:

15 Club View Cir

Sallisaw, OK 74955

County: Sequoyah

Year Built: 1998

GPS Coordinates: <u>35.44639,-94.77349</u> Drive Time: <u>1 hr</u>



Directions: From Cherokee Nation, From Cherokee St in Sallisaw go S on Wheeler Ave 0.7 mi take a slight left on E Delaware Ave go 3/4 mi turn left on Club View Cir house is on the left

Maurice Gifford 918-506-9860

Cost Estimator/Inspector

5/15/25

Date

WorkWrite-Up and Bid Document/By Trade

Celia Logan 15 Club View Cir Sallisaw, OK		Conta	ractor Name:			
(479) 285-4885		Contract	or Signature:			
			7	This document must be signed to be a valid bid.		
		PROJECT TYPE: Emergen		epairs	Bid Due Date:	
Trade	Work De	escription / Comments		Gen. Spec.	Qty Unit	Item Bid
Site Work			The state of the s			Alein Dil
1 Area: PROFESSIONAL SERVICE Tree/Remove/13" to 18" diameter. Remove tree/13" to 18" diameter. Fill				Div.# 2.R	3 Ea	
grade area.						
Three trees in back around them	yard that are ha	anging over the house. All	l trees have rib	oons tied		
	SSIONAL SERV			Div.# 2.R	1 Ea	
Tree/Remove/19" to 24" diameter. Remove tree/19" to 24" diameter. Fill hole and regrade area.						
Tree on north side of	of house that lim	nb has fell out of.				
3 Area: PROFES	SIONAL SERV	/ICE		Div.# 2.R	1 Ea	
Tree/Remove/25" to 36" diameter. Remove tree/25" to 36" diameter grade area.			ameter. Fill ho	e and re-	I Ca	
Tree in front of hous	e with vines on	it and				

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
installation page Based Paint r	on shall be in accordance with local codes, manufrocedures, good quality workmanship practices, Grequirements when applicable. Conflicts between with the more stringent requirement.	Seneral Specifications	and Lead-	tal: