

HACN HOUSING REHAB SITE DIRECTIONS

Participant: Robyn Pizana

Telephone: Home:

(918) 773-2911

Business:

Mobile

(479) 883-9125

Address:

456961 E 1063 Rd

Vian OK 74962

County:

Sequoyah

Year Built: 1999

GPS Coordinates: 35.47422,-94.88594



Directions: From Cherokee Nation, Continue to US-62 w 16 sec (203 ft) Continue to Sequoyah County 29 min (23.7 mi) Turn left onto State Hwy 82 S 10 min (8.4 mi) Turn left onto US-64 E/Schley St Continue to follow US-64 E 6 min (5.9 mi)

Follow S 4570 Rd/McKey Rd/N4570 Rd to 1043

Rd/E 1063 Rd 1 min (0.8 mi) 456961 E 1063 Rd Vian, OK 74962

Larry Ketcher

06/10/2025

Cost Estimator/Inspector

Date



Housing Authority of the Cherokee Nation PO Box 1007, Tahlequah, Oklahoma 74465-1007 918-456-5482 | 1-800-837-2869

iption	Quantity	Per
MATE: Emergency (Housing Authority of the Cherokee Nation)	Claim #11942, Robyn I	Pizan
ROOFPLAN: Roofplan		
Roof, Roof 2, Roof 3, Roof 4, Roof 5		
Roof area: 2,789.60 SF Squares: 27.9 SQ Soffit: 540.65 SF Eaves: 208.09 LF Ridge: 66.62 LF		1
1 ITEL, Shingles, 3-Tab, Remove	27.92	SQ
2 Shingles, Composition, Laminated/Architectural, Good - Replace	27.92 (30.71)	SQ
Includes 10% waste on material quantity.		,
3 Shingles, Starter Row, Continuous - Replace	253.43 (278.77)	LF
Includes 10% waste on material quantity.		
4 Drip Edge, Eave/Rake, Aluminum, Pre-Finished Color - Replace	253.43 (266.11)	LF
Includes 5% waste on material quantity.		
5 Valley Flashing, Aluminum - Replace	141.02 (148.08)	LF
Includes 5% waste on material quantity.		
6 Roof Vent, Static, Box/Turtle, Aluminum - Replace	4	EA
7 Felt, Synthetic, Good - Replace	27.92	SQ
8 Vent Pipe Flashing, Furnace, Aluminum, 4" - Replace	2	EA
one is 4" and the other is 6", Furnace and water heater roof jack.		-
9 Ridge Cap Shingles, Laminated/Architectural - Replace	132.46 (145.72)	LF
Includes 10% waste on material quantity.		-

Date: ____ Contractor Signature: ____