

HACN HOUSING REHAB SITE DIRECTIONS

Name: Lucille Nofire

Telephone: (479)719-5510

Address:

474216 State Hwy 101

Muldrow, OK 74948

County: Sequoyah

Year Built: 1963

GPS Coordinates: <u>35.53587,-94.56743</u> Drive Time: <u>1hr</u>





Directions: From Cherokee Nation, From Hwy 59&101 N of Sallisaw go East on 101 13 mi and house is on the right

Maurice Gifford 918-506-9860

G . F .: A

Cost Estimator/Inspector

7/23/24

Date

WorkWrite-Up and Bid Document/By Trade

	WOIKWILLE-	op ana bia b	ocument by True	ie	
Lucille Nofire 474216 State Hwy 101 Muldrow, OK (479) 719-5510		7-49 Contractor Signature:			
		This document mu		st be signed to be a valid bid.	
		PROJECT TYPE: Rel	habilitation	Bid Due Date:	
Trac	de Work Description	on / Comments	Gen. Spec.	Qty Unit	Item Bid
Car	pentry				
1	Area: EXTERIOR		Div.# 8.Q	16 LF	
	r Trim/Exterior/Replace. Replace doo at (two coats).	r trim, exterior. Work sh	all include prep and		
•	lace brick mold around front door				
2	Area: KITCHEN		Div.# 10.G	1 Ea	Prince de la company de company d
Fire	Extinguisher/Install. Install new fire ea	xtinguisher.			
3	Area: BEDROOM #3		Div.# 9.L.3	180 SF	
Ove	rlay sub-floor with 3/8 AC plywood.				
4	Area: EXTERIOR		Div.# 6.R	1 Ea	-
	rs/Exterior/Wood/Replace. Replace e				
	e. Work shall include 2"X6" handrails of back deck	& Balusters on each sid	e.		

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry				
5 Area: EXTERIO	R	Div.# 8.B	1 Ea	
Storm Door/White Vi 298-SS or written ap	nyl Clad/Install. Install new storm door, vinyl c proved equal.	lad.Use Larson model		
On front of house				
6 Area: EXTERIO	PR	Div.# 14.B.	20 Ea	
Storm Window/Instal	I new aluminum fram storm window			
7 Area: BEDROC	M #1	<i>Div.</i> # 6.N	80 LF	
Trim/1" x 2" trim mol	ding /Replace. Replace trim, 1" x 2" trim moldi	ing.		
Batt joints on ceiling	with 1x2s and caulk before painting			
8 Area: EXTERIO	DR .	Div.# 15.C.	680 SF	
, ,	oam Sheathing/Install new vinyl siding with 3/8 all include repairs to all covered surfaces to all			
	across front of house and on west end and m a. wrap 1x4s around windows with metal	asonite siding on west		
9 Area: EXTERIO	DR .	Div.# 6.P	98 LF	
Window Trim/Exterio	or/Interior/Replace exterior/interior window trim	. Match existing.		
Replace all 1x4s aro	und 7 ext windows where new siding is installed	ed. Exterior only		
Drywall & Finish				
10 Area: BEDROO	OM #3	Div.# 9.D	48 SF	
	" drywall. Finish completely. Work shall include	e tape, bed and texture		
to match existing sur				

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Drywall & Finish				
11 Area: BEDRO	OM #3	Div.# 9.D	32 SF	
	ce 1/2" drywall on wall/Finish completely. Work and paint to match existing surfaces.	shall include		
Electrical				
12 Area: INTERIO	OR .	<i>Div.</i> # 13.D. 11	4 Ea	
	attery Operated/Install new smoke detector, batt bedrooms and hallways adjacent to bedrooms. qual.			L
Flooring				
13 Area: BEDRO	OM #1	Div.# 9.L	24 SY	
	g/Install new vinyl floor covering & shoe mold. I nanufacturer year warranty. Use a heavy floor ro			L
14 Area: BEDRO	OM #3	Div.# 9.L	20 SY	
	g/Install new vinyl floor covering & shoe mold. I nanufacturer year warranty. Use a heavy floor ro			
Paint & Finish				
15 Area: BEDRO	OM #3	Div.# 9.N.3	560 SF	
	ngs, Walls, & Trim /Paint Two coats, . Work sha SF=ACTUAL SURFACE AREA OF WALLS &			
16 Area: BEDRO	OM #1	Div.# 9.N.3	218 SF	

Plumbing

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing				
17 Area: UTILITY	ROOM #1	Div.# 11.A	1 Ea	
new 40 gal. electric	ric/40 Gallon/Replace. Replace existing Electric water heater. Install new electric water heater I hook-ups, shut off valves and plumbing.			
installation proce Based Paint requi compliance with the for conducting sa Workers. Asbesto	shall be in accordance with local codes, man dures, good quality workmanship practices, irements when applicable. Conflicts between the more stringent requirement. Contractor a ife work practices that comply with OSHA Co is report, where required, will be attached if a s Sampling Report for location and testing o	General Specifications an requirements will be resumed the job will be resumented the job will be repostruction Standards for areas tested are 1% or greaters.	nd Lead- solved by sponsible Asbestos eater. See	d: