

## HACN HOUSING REHAB SITE DIRECTIONS

Name: Jerry Frye

Telephone: (918) 208-4596

Address:

E1111 rd

Sallisaw, OK 74955

County: Sequoyah

Year Built: 2000

GPS Coordinates: <u>35.40501,-94.82020</u> Drive Time: <u>1hr</u>





**Directions:** From Cherokee Nation, From I-40 take exit 308 toward Sallisaw/Poteau turn right on 59-S go 2.2 mi turn right on E1105 rd/Wild horse mountain rd go 3/4 mi turn left on 4606 rd then turn right on 1106 rd then go S on 4606 rd go 1/2 mi turn left on E1111 rd go 0.2 mi house on the left

Maurice Gifford 918-506-9860

Cost Estimator/Inspector

6/19/24

Date

## WorkWrite-Up and Bid Document/By Trade

Jerry Frye	Contractor Name:			
E 1111 rd Sallisaw, OK 7-4955	Contractor Signature:			
	Th	is document must b	This document must be signed to be a valid bid.	d.
	PROJECT TYPE: Rehabilitation		Bid Due Date:	
Trade Work Descrip	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Carpentry				
1 Area: BATHROOM #1		Div.# 11.4.	4 SF	
Sinktop/Cultured Marble/Integral Sink. Replace existing sinktop with new cultured marble sink top with integral sink. Include new drain line, trap & Delta faucet.	keplace existing sinktop with new culton drain line, trap & Delta faucet.	ured marble		
Area: BATHROOM #1		Div.# 6.D.	30 SF	
Subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood.	Replace subfloor with new 3/4" smoot	th plywood.		
Area: BEDROOM #1		D::: # 6 D	22 00	
Subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood	Replace subfloor with new 3/4" smoot	h plywood		
Replace small area at door entrance fold back carpet and put back down	back carpet and put back down	•		
Area: BEDROOM #3		Div.# 6.D.	150 SF	
Subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood	Replace subfloor with new 3/4" smoot	h plywood.		
Area: HALLWAY #2		Div.# 6.D.	24 SF	
subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood	Replace subfloor with new 3/4" smootl	h plywood.		
itchen area				

Trade Work Description / Comments Gen. Spec.	Oty Unit	Hom Bid
Carpentry	10	
6 Area: KITCHEN Div.# 6.D.	150 SE	
Subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood	0	
Cut around cabenits as close as possible		
7 Area: UTILITY ROOM #1 Div.#6.D	20 SE	
Subfloor/ Remove the existing flooring. Replace subfloor with new 3/4" smooth plywood	9	
8 Area: BATHROOM #1 Div. # 6.0	2LF	
Vanity Base Cabinet/Pre-Finished Oak. Replace existing vanity with new pre-finished oak vanity base cabinet.	!	
9 Area: EXTERIOR Div.# 16.A.	41 LF	
Wheel Chair Ramp/Wood/Install 4' inside clear space wheel chair ramp/pressure treated lumber work includes balusters, handrails, guardrails, concrete landing at the end of ramp.		
replace 6x6 deck and ramp at front door		
Flooring		
10 Area: BATHROOM #1  Div.# 9.L  Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.	388	
11 Area: BEDROOM #3  Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.	17 SY	
12 Area: HALLWAY #2  Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.	384	
Print Date: Thursday, June 20, 2024 E 1111 rd Sallisaw, OK 7-4955		Page 2 of 3

Total:	nd Lead- olved by sponsible Asbestos ater. See	All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See attached Asbestos Sampling Report for location and testing of Planned Work Activities.
	1216 SF	16 Area: ROOF  Roof/Repair Mobile Home Roof /Apply ANVIL ROOF-TEC Acrylic White Elastomeric Roof Coating. Remove loose material before appyling the new material. Apply Material according to manufactures recommendations. 2 Coats  Use Kool seal roll on 2 coats
	<u>1</u> П а	Plumbing  15 Area: BATHROOM #1  Commode/Install new commode, seat, supply line, shutoff, flange and wax seal. Use American Standard Cadet or written approved equal.
	58Y	14 Area: UTILITY ROOM #1  Div.# 9.L  Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.
	17 SY	13 Area: KITCHEN  Div.# 9.L  Vinyl Sheet Flooring/Install new vinyl floor (sheet) covering & shoe mold. Minimum 12 mil wear layer and 10 year manufacturer year warranty.
Hem Bid	Qty Unit	Trade Work Description / Comments Gen. Spec.

Print Date: Thursday, June 20, 2024

E 1111 rd Sallisaw, OK 7-4955

Page 3 of 3