

HACN HOUSING REHAB SITE DIRECTIONS

Name: Mary Speirs

Telephone: (918)999-2395

Address:


110 Countryside Ln

Roland, OK 74954

County: Sequoya

Year Built: 1950

GPS Coordinates: 35.40643, -94.53479 Drive Time: 1 Hr



Directions: From Cherokee Nation, Take D0790 Rd/W Willis Rd to US-62 W in Tahlequah 2 min (0.8 mi) Continue to Sequoyah County 28 min (24.1 mi) Get on I-40 E 12 min (9.5 mi) Follow I-40 E to Countryside Ln 25 min (27.8 mi) Turn right onto Countryside Ln Destination will be on the right 27 sec (423 ft) 110 Countryside Ln Roland, OK 74954

Rodney Carman (918) 506-9858 Cost Estimator/Inspector 2/7/2024

Date

WorkWrite-Up and Bid Document/By Trade

		enquesare and a second and a se
	be signed to be a vali	d bid.
tion	Bid Due Date:	
Gen. Spec.	Qty Unit	Item Bid
Din#13.D. 1.	<u>т</u>	
Disconnect Box,		
ve extra breaker bring to code		
Dip.#11.A	1500 SF	
(w/PVC) in/under es, Stand Pipe		Programme of the Control of the Cont
Div.#11.A	1 ma	
ring, shutoff		
	(918) 999-2395 This document must PROJECT TYPE: Rehabilitation PROJECT TYPE: Rehabilitation This document must PROJECT TYPE: Rehabilitation Div.# 13.D. 1 Area: EXTERIOR 1 Area: EXTERIOR 1 Area: EXTERIOR 2 Area: CRAWLSPACE Replace/Entire Structure. Replace all water lines (w/PEX) & drain lines (w/PVC) in/lunder structure. Include shutoffs/supply line connections to all fixtures/appliances, Stand Pipe for washer drain. SF=FLOOR AREA. 3 Area: BATHROOM #1 Commode/Remove & Reinstall. Remove existing commode, replace wax ring, shutoff and supply line and when re-installing.	ent must be sig

OCT STATE OF THE PROPERTY OF T	ded s and Lead- resolved by responsible for Asbestos greater. See ies.	All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See attached Asbestos Sampling Report for location and testing of Planned Work Activities.
		Shower/Acrylic fiberglass/Pre-Fab/3 Piece. Replace existing bathtub/shower combination with new 3 piece fiberglass shower unit. Include all related plumbing and sheetrock. Delta fixture.
ir actin datin firms on	TI CO	8 Area: BATHROOM #1 Div.# 11.A
		Lavatory-Drain/Replace the drain pipe and trap. Replace sink drain, drain lines, shutoffs valves and supply lines. Reinstall existing lavatory/vanity.
	m m	7 Area: BATHROOM #2 Div.# 11.A.
		Lavatory-Drain/Replace the drain pipe and trap. Replace sink drain, drain lines, shutoffs valves and supply lines. Reinstall existing lavatory/vanity.
	1 1 1 1	6 Area: BATHROOM #1 Div.#11.A.
		Faucet/Kitchen/Single Handle/Goose Neck. Replace kitchen faucet with new single handle goose neck faucet, supply lines & shutoffs. Includes Sprayer.
	LLI LLI LLI LLI LLI LLI LLI LLI LLI LLI	5 Area: KITCHEN Div.#11.A
		Commode/Remove & Reinstall. Remove existing commode, replace wax ring, shutoff and supply line and when re-installing.
	m m	4 Area: BATHROOM #2 Div.#11.A
		Plumbing
liem Bid	Qty Unit	Trade Work Description / Comments Gen. Spec.