

Number 1: Scope for West Siloam Springs:

Water tank inspection for West Siloam

Engage vendor to perform a 5 year internal inspection of 300,000 gallon water tank at WSS casino IAW appropriate NFPA Standard. A full report of inspection is required as well as pictures

Number 2: Scope for Will Rogers Downs:

This scope of work is for the Will Rogers Downs 5 year 36,000 gallon water tank inspection.

Perform an interior in-service inspection and exterior inspection of the tank that meets the requirements of the National Fire Protection Association (NFPA).

Provide a detailed report of the findings of the inspection, including photographs, DVD, and recommendations and cost estimates for any repairs, if needed.

All materials required for inspection will be provided by the vendor.