WorkWrite-Up and Bid Document/By Trade

Galela Caughman	Contractor No	ame:			
802 Byrd Avenue Sallisaw, OK (918) 840-0157	7-4955 Contractor Signa	uture:			
(5.5) 5.5 5.5.		This document mus		t be signed to be a valid bid.	
	PROJECT TYPE: Rehab	PROJECT TYPE: Rehabilitation		Bid Due Date:	
Trade Work Do	escription / Comments	Gen. Spec.	Qty Unit	Item Bid	
Carpentry					
1 Area: KITCHEN		<i>Div.</i> # 10.G	1 Ea		
Fire Extinguisher/Install. Install new	w fire extinguisher.				
Electrical		3			
2 Area: INTERIOR		<i>Div.</i> # 13.D. 11	5 Ea		
Smoke Detector/Battery Operated, lithium battery). All bedrooms and written approved equal.				Newson and the second	
Install in hallway, kitchen and all be	edrooms.	*			
HVAC		*			
3 Area: ROOF		<i>Div.</i> # 12	1 Ea		
HVAC Equipment/Central/Cooling					
equipment (13 SEER). INSIDE FU COIL, EVAP, NEW DISCONNECT Change out.					
Plumbing			· · · · · · · · · · · · · · · · · · ·		

Print Date: Friday, July 6, 2018

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing				
Area: GARAGE		<i>Div.</i> # 11.A	1 Ea	
gal. gas water heater	Gallon/Replace. Replace existing gas water Work shall include elevating to 18" (if in gar air, gas & electrical hook-ups for code legal in	age), replacement of		
Roofing				
Area: ROOF		Div.# 7.A.	26 Sq	
Pipe Flashing, Valley	key/Tamko or written approved equal. 30 lb For Flashing. shingles, contractor is responsible for remover.			
6 Area: ROOF		Div.# 7.A	96 SF	
Sheathing/5/8" CDX/ Replace all deteriora	Replace. Replace existing sheathing/Use 5/8	"CDX.		
installation proced Based Paint requir compliance with the for conducting saf Workers. Asbestos	nall be in accordance with local codes, manures, good quality workmanship practices ements when applicable. Conflicts between a more stringent requirement. Contractor is work practices that comply with OSHA Contractor, where required, will be attached its Sampling Report for location and testing	s, General Specifications a en requirements will be re awarded the job will be re construction Standards fo f areas tested are 1% or g	and Lead- esolved by esponsible r Asbestos reater. See	al:

Galela Caughman-site directions, highway 59 to Sallisaw turn left on East Redwood Street, then left at Sam Ed Bush Dr.

802 Byrd Avenue, Sallisaw Ok. 74955

Phone #918-840-0157