

## HACN HOUSING REHAB SITE DIRECTIONS

Name: Keri Sears

Telephone: (918) 534-7538

Address:

116 NE Howard Ave

Bartlesville, OK 74006

County: Washington

Year Built: 1946

GPS Coordinates: 36.75786,-95.93956 Drive Time: 1HR 43MIN



**Directions:** From Cherokee Nation, Get on OK-165 N/OK-351 in Muskogee County 21 min (19.9 mi) Head southwest on US-62 W/S Muskogee Ave toward S 504 Rd Continue to follow US-62 W 19.4 mi Use the right lane to merge onto OK-165 N/OK-351 via the ramp to Tulsa/Port of Muskogee 0.4 mi

• Continue on OK-351. Take OK-51 W to OK-11 W/US-75 N in Tulsa. Take the US 75/US 75 N/OK-11 W exit from OK-11 W 43 min (50.8 mi)

Merge onto OK-165 N/OK-351 Continue to follow OK-351 Toll road 33.5 mi Continue onto OK-51 W 6.0 mi Take the exit onto US-169 N toward Owasso 4.5 mi Use the right 2 lanes to merge onto I-244 W/US-412 W toward Okla City 1.3 mi Take exit 12B for OK-11 W toward Tulsa International Airport 0.6 mi Continue onto OK-11 W 4.6 mi Take the exit onto OK-11 W/US-75 N toward Bartlesville0.4 mi Follow US-75 N to NE Howard Ave in Bartlesville 40 min (39.1 mi) Merge onto OK-11 W/US-75 N Continue to follow US-75 NPass by Chili's Grill & Bar (on the left in 36.2 mi)38.8 mi Turn left onto Tuxedo Blvd 0.2 mi Turn right onto NE Howard Ave Destination will be on the right 308 ft

116 NE Howard Ave Bartlesville, OK 74006.

Larry Ketcher	5/1/2025	
Cost Estimator/Inspector	Date	

## WorkWrite-Up and Bid Document/By Trade

<b>Keri Sears</b> 116 NE Howard Ave bartlesville, OK (918) 534-7538	7-400 Contractor Signate	Market Market Schools and Control of Control			
		This document mus	This document must be signed to be a valid bid.		
	PROJECT TYPE: Emerge	ency Repairs	<b>Bid Due Date</b>		
Trade Work Descript	ion / Comments	Gen. Spec.	Qty Unit	Item Bid	
Electrical					
1 Area: EXTERIOR		<i>Div.</i> # 13.D. 22	1500 SF		
Rewire Elect.System/Entire House. Rep fixtures, Hard wired Smoke Detectors an can and weather head.	lace all wiring, outlets, switch d ceiling fans. Include 200 A	nes, GFCI, light mp service, meter			
Bedroom #1 only has one outlet, add out	lets to Bedroom.				
All construction shall be in accordance installation procedures, good quality Based Paint requirements when applicompliance with the more stringent re	workmanship practices, G icable. Conflicts between i	eneral Specifications	and Lead-	al:	