

Lead Hazard Control Visual Clearance Form

Date 6/22/09

Name of Clearance Examiner Ashley Wagnon

License Number OKRASR13320, CNRASR00018

Name of Property Owner _____

Property Address 339 N. Sycamore, Nowata, OK 74048

Date Cleanup Completed 6/12/09

Time Cleanup Completed 12:00 pm

Abatement/Interim Control Contractor Name Michael Connelly, Connelly Bros. Construction Inc.

Address 621 South Holly, Sallisaw, OK 74955

Telephone No. 918-775-5436

Check if repeat clearance examination

Room ID	Building components requiring treatment	Work completed? (yes or no)	Paint Chips? (yes or no)	Dust? (yes or no)	Additional Work Required?
Rm 1, Foyer	Wall B Door Casing	Yes	No	No	No
Rm 1, Foyer	Wall C Window Casing	Yes	No	No	No
Exterior	Wall A&D Cornerboards	Yes	No	No	No
Exterior	All wood/tan soffit	Yes	No	No	No
Exterior	All wood/brown fascia	Yes	No	No	No

Exterior Soil Treated Not Treated

If treated, is bare soil present Yes No

Was contaminated soil removed? Yes No

Is additional soil treatment required? Yes No

Signature *Ashley Wagnon*

Lead Hazard Control Dust Sampling Form

Date 6/22/09

Name of Clearance Examiner Ashley Wagnon

License Number OKRASR13320, CNRASR00018

Name of Property Owner _____

Property Address 228 N. Sycamore, Nowata, OK 74048

Clearance Categories:

1. Interior treatments without containment.
2. Interior treatments with containment.
3. Exterior work on painted surfaces.
4. Routine maintenance.
5. Soil work.

Sample Number	Room Identifier	Surface Type	Clearance Category	Dimensions of Sample	Result of Lab Analysis ($\mu\text{g}/\text{ft}^2$)	Pass or Fail
01	Rm 1 Foyer	Floor	2	12 x 12	<16.00	Pass
02	Rm 1 Foyer	Window Sill	2	3.5 x 12	<54.79	Pass
07	Exterior(A)	Floor	2	12 x 12	<16.00	Pass
08	Exterior (A)	Window Sill	2	1.5 x 12	<128.00	Pass

Total Number of Samples on this Page 4

Page 1 of 1

Date of Sample Collection 06/18/09 Date Shipped to Lab 06/18/09

Shipped by Jerry Cochran Received by Barbara Holder
 (Signature) (Signature)

Lead Hazard Control Clearance Soil Sampling Form

Date 6/22/09

Name of Clearance Examiner Ashley Wagnon

License Number OKRASR13320, CNRASR00018

Name of Property Owner

Property Address 228 N Sycamore, Nowata, OK 74048

Sample Number	Location	Bare or Covered	Lab Result (µg/g)	Pass or Fail
09	Exterior (Dripline)	Bare	364.17	Pass

Total Number of Samples on this Page 1

Page 1 of 1

Date of Sample Collection 6/18/09 Date Shipped to 6/18/09

Shipped by: Jerry Cochran Received by Barbara Holder
(Signature) (Signature)