

Lead Hazard Control Visual Clearance Form

Date 09/5/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner #10822

Property Address 406 E. Poplar Ft. Gibson, Ok. 74434

Date Cleanup Completed 08/30/08

Time Cleanup Completed 4 pm

Abatement/Interim Control Contractor Name Rycon E & C, Inc.

Address 213 River St. Commerce, Ok. 74339

Telephone No. (918) 675-5604

Check if repeat clearance examination ☐


Room ID	Building components requiring treatment	Work completed? (yes or no)	Paint Chips? (yes or no)	Dust? (yes or no)	Additional Work Required?
Ext	A Wall	Yes	No	No	No
Ext	A Fascia	Yes	No	No	No
Ext	A Soffit	Yes	No	No	No
Ext	A Left Window	Yes	No	No	No
Ext	A Center Window	Yes	No	No	No
Ext	A Right Window	Yes	No	No	No
Ext	A Door	Yes	No	No	No
Ext	A Garage Trim	Yes	No	No	No
Ext	B Wall	Yes	No	No	No
Ext	B Fascia	Yes	No	No	No
Ext	B Soffit	Yes	No	No	No
Ext	B Right Window	Yes	No	No	No
Ext	C Fascia	Yes	No	No	No
Ext	C Soffit	Yes	No	No	No
Ext	C Left Window	Yes	No	No	No
Ext	C Center Window	Yes	No	No	No
Ext	D Wall	Yes	No	No	No
Ext	D Fascia	Yes	No	No	No
Ext	D Soffit	Yes	No	No	No
Ext	D Left Window	Yes	No	No	No
Ext	D Right Window	Yes	No	No	No

Exterior Soil ☐ Treated ☒ Not Treated

If treated, is bare soil present ☐ Yes ☐ No

Was contaminated soil removed? ☐ Yes ☐ No

Is additional soil treatment required? ☐ Yes ☐ No

Signature  9-5-08

Lead Hazard Control Dust Sampling Form

Date 09/5/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner #10822

Property Address 406 E. Poplar Ft. Gibson, Ok. 74434

Clearance Categories:

1. Interior treatments without containment.
2. Interior treatments with containment.
3. Exterior work on painted surfaces.
4. Routine maintenance.
5. Soil work.

Sample Number	Room Identifier	Surface Type	Clearance Category	Dimensions of Sample	Result of Lab Analysis ($\mu\text{g}/\text{ft}^2$)	Pass or Fail
01	Ext.	Floor	3	12 x 12	<16.00	Pass
02	Ext	Win Sill	3	2 x 20	<57.55	Pass

Total Number of Samples on this Page 2

Page 1 of 1

Date of Sample Collection 9/3/08 Date Shipped to Lab 9/3/08

Shipped by Shaun West Received by Jeff Mlekush
(Signature) (Signature)

Lead Hazard Control Clearance Soil Sampling Form

Date 09/5/08

Name of Clearance Examiner Shaun West

License Number OKRASR11453, CNRASR00001

Name of Property Owner #10822

Property Address 406 Poplar Ft. Gibson, Ok. 74434

Sample Number	Location	Bare or Covered	Lab Result ($\mu\text{g/g}$)	Pass or Fail
03	Ext. Drip	Bare	< 57.78	Pass

Total Number of Samples on this Page _____

Page 1 of 1

Date of Sample Collection 9/3/08 Date Shipped to lab 9/3/08

Shipped by Shaun West
(Signature)

Received by Jeff Mlekush
(Signature)