WorkWrite-Up and Bid Document/By Trade

Bridget Walker	Contractor Name:		
311 W. Seneca Nowata, OK 7-4048 (918) 504-1555	Contractor Signature:		a w
	This docum	This document must be signed to be a valid bid	valid bid.
PROJE	PROJECT TYPE: Rehabilitation	Bid Due Date:	te:
Trade Work Description / Comments	iments Gen. Spec.	ec. Qış Unit	Item Bid
Carpentry			52N XX
1 Area: KITCHEN	<i>Div.</i> # 10.G	0.G 1 Ea	
Fire Extinguisher/Install. Install new fire extinguisher.	er.		1500
Electrical			
2 Area: INTERIOR	<i>Diν.</i> # 13.D. 11	13.D. 5 Ea 11	
Smoke Detector/Hard Wired with Battery Back-Up/Install new smoke detector, hard wired with battery backup. All bedrooms and hallways adjacent to bedrooms. Use Firex #045186 or written approved equal.	/Install new smoke detector, hard vadjacent to bedrooms. Use Firex	wired	1 MANA 1
HVAC			
3 Area: GARAGE	Div.# 12	2 1 Ea	
HVAC Equipment/Central/Heating & Cooling 3 Ton/13 SEER & Propane Gas Heating Replace INSIDE AND OUTSIDE EQUIPMENT/INCLUDING; COPPER LINES, A- COIL & Coil BOX, OUTSIDE CONDENSOR; ALL VENT PIPE, Filter Grill, ceiling Registers	2007/13 SEER & Propane Gas Heating 2007/20 COPPER LINES, A-CO 2007/20 Propagation of the Propagation of th		
and new coderisate line.			
Olimbina			
Plumbing			

Trade Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
Plumbing	140		
4 Area: GARAGE	Div.# 11.A	1 Ea	
Water Heater/ Natural Gas/40 Gallon. Replace water heater with a new 40 gal gas water heater. Work shall include elevating to 18" (if in garage), TPR, combustion air, Gas Flex line, Flex water supply connections, and drain Pan. Code Legal Installation.	gal gas water air, Gas Flex		
Roofing		A	
5 Area: ROOF	Div.# 7.A.	30 Sq	
Roofing/Heritage/30 Year Warranty. Install fiberglass shingles/Minimum 30 year warranty/Use Marlarkey/Tamko or written approved equal. 30 lb Felt, Painted Style D Drip Edge, Pipe Flashing, Valley Flashing, and Metal Slant Back Vents.	year d \$tyle D		
6 Area: ROOF	Div.# 7.A	96 SF	
Sheathing/5/8" CDX/Replace. Replace existing sheathing/Use 5/8" CDX.			
Replace all deteriorated decking.	4.		

attached Asbestos Sampling Report for location and testing of Planned Work Activities. Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Based Paint requirements when applicable. Conflicts between requirements will be resolved by installation procedures, good quality workmanship practices, General Specifications and Lead-All construction shall be in accordance with local codes, manufacturers' recommended Bridget Walker-site directions: From jct. of 169 and 60 hwy in Nowata go south on Maple street 3 blocks to Seneca then west 2 blocks home on south side of the street.