



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 336903	Client: Cherokee Nation Environmental Programs
Account Number: C162	Logan Girty
Date Received: 07/12/2021	PO Box 948
Received By: Cyonne Harrod	Tahlequah, OK 74464
Date Analyzed: 07/14/2021	Project: Linda Harmon
Analyzed By: Cassie Sanborn	Project Location: Tulsa
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	01-01	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
001a		Layered	Tan Texture	Asbestos Present Chrysotile 2	NA	CaCO3 Paint
001b		Layered	White Drywall	Asbestos Not Present	Cellulose 10	Gypsum
002	01-02	Layered	White Texture	Asbestos Not Present	NA	CaCO3 Paint
002a		Layered	Tan Texture	Asbestos Present Chrysotile 2	NA	CaCO3 Paint
003	01-03	Homogeneous	Tan Texture	Asbestos Present Chrysotile 2	NA	CaCO3 Paint
004	02-01	Layered	Tan Sheet Vinyl	Asbestos Not Present	Cellulose 20	CaCO3 Vinyl

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.

NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 336903	Client: Cherokee Nation Environmental Programs
Account Number: C162	Logan Girty
Date Received: 07/12/2021	PO Box 948
Received By: Cyonne Harrod	Tahlequah, OK 74464
Date Analyzed: 07/14/2021	Project: Linda Harmon
Analyzed By: Cassie Sanborn	Project Location: Tulsa
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
004a		Layered	Tan Leveling Compound	Asbestos Not Present	NA	CaCO3

Cassie Sanborn

Cassie Sanborn, Laboratory Analyst

7/14/2021

Date of Report

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.

NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



ASBESTOS CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

For Lab Use Only	
Lab No. <u>336903</u>	
<input checked="" type="checkbox"/> Accept	<input type="checkbox"/> Reject

Contact Information		Project Information		Report Results (<input checked="" type="checkbox"/> one box)	
Company: Cherokee Nation Environmental Programs	Phone: (918) 453-6140	Project Name: Linda Harmon		<input type="checkbox"/> QuanTEM Website	
Contact: Logan Girty	Cell Phone: (918) 772-8346	Project Location: Tulsa		<input checked="" type="checkbox"/> Email logan-girty@cherokee.org	
Account #: C 162	E-mail: logan-girty@cherokee.org	Project ID:		<input type="checkbox"/> Other _____	
SAMPLED BY: Name: Logan Girty	Date: 7-9-2021	P.O. Number: 260136			

RELINQUISHED BY	DATE & TIME	VIA	RECEIVED BY	DATE & TIME
<i>Logan E Girty</i>	7.9.2021	Fed Ex	<i>[Signature]</i>	7/12 8:30
	4:00 PM			

REQUESTED SERVICES (Please the Appropriate Boxes)

PLM	PLM	TEM	TEM	TURNAROUND TIME
<input checked="" type="checkbox"/> Bulk Analysis (EPA 600/R-93/116)	<input type="checkbox"/> Vermiculite Attic Insulation (EPA 600/R-04/004)	<input type="checkbox"/> Air- AHERA	<input type="checkbox"/> Bulk- Presence / Absence EPA600/R-93/116	<input type="checkbox"/> Rush
<input type="checkbox"/> 400 Point Count	<input type="checkbox"/> Other	<input type="checkbox"/> Air- NIOSH 7402	<input type="checkbox"/> Bulk- Quantitative (weight%)- Charfield	<input type="checkbox"/> Same Day
<input type="checkbox"/> 1000 Point Count		<input type="checkbox"/> Air- ISO 10312	<input type="checkbox"/> Dust- Presence / Absence	<input type="checkbox"/> 24 - Hour
<input type="checkbox"/> Gravimetric Preparation	PCM	<input type="checkbox"/> Drinking Water- EPA 100.2	<input type="checkbox"/> Dust- Quantitative (fibers/sq.cm)- ASTM D5755	<input checked="" type="checkbox"/> 3 - Day
<input type="checkbox"/> Particle ID	<input type="checkbox"/> NIOSH 7400	<input type="checkbox"/> Waste Water- EPA 600/4-83-043	<input type="checkbox"/> Other	<input type="checkbox"/> 5 - Day

No.	Sample ID (10 Characters Max)	<input checked="" type="checkbox"/> To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	01-01	<input checked="" type="checkbox"/>	Blue	Drywall Texture		Bathroom 1
2	01-02	<input checked="" type="checkbox"/>	Blue	Drywall Texture		Bathroom 1
3	01-03	<input checked="" type="checkbox"/>	Blue	Drywall Texture		Bathroom 1
4	02-01	<input checked="" type="checkbox"/>	Tan	Roll Sheet Vinyl Flooring		Bathroom 1
5		<input type="checkbox"/>				
6		<input type="checkbox"/>				
7		<input type="checkbox"/>				
8		<input type="checkbox"/>				
9		<input type="checkbox"/>				
10		<input type="checkbox"/>				

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"
 Please Note - UPS and USPS are NOT available for Saturday Delivery