

# Work Write-Up and Bid Document/By Trade

**Sharon Cowart**  
 600 North Hwy 10 Gore, OK 7-4435  
 (918) 774-5585

Contractor Name: \_\_\_\_\_  
 Contractor Signature: \_\_\_\_\_

*This document must be signed to be a valid bid.*

**PROJECT TYPE: Rehabilitation**

**Bid Due Date:**

Trade	Work Description / Comments	Gen. Spec.	Qty Unit	Item Bid
<b>HVAC</b>				
1	<b>Area: HVAC</b> Ductwork/Install new ductwork/SF = air conditioned floor area. Install supply and return air ductwork. Seal return air plenums including boxes under(Split Unit) unit and closet ceiling to insure no Attic air is pulled into unit. <b>replace complete ductwork system includeing return and registers</b>	Div.# 12	1800 SF	
2	<b>Area: HVAC</b> HVAC EQUIPMENT REPLACEMENT/ Heating & Cooling, Install 4 TON/13 or14 SEER, PACKAGE UNIT Electric Heat & A/C. ALL NEW Duct work, Vent registers , Thermostat, Return air grill, all necessary electrical wiring, for a complete installation.	Div.# 12	1 Ea	

**Total:**

**All construction shall be in accordance with local codes, manufacturers' recommended installation procedures, good quality workmanship practices, General Specifications and Lead-Based Paint requirements when applicable. Conflicts between requirements will be resolved by compliance with the more stringent requirement. Contractor awarded the job will be responsible for conducting safe work practices that comply with OSHA Construction Standards for Asbestos Workers. Asbestos report, where required, will be attached if areas tested are 1% or greater. See attached Asbestos Sampling Report for location and testing of Planned Work Activities.**



# HACN HOUSING REHAB SITE DIRECTIONS

---

Name: Sharon Cowart

Telephone: (918)489-2873

Address: 600 North Hwy 10  
Gore, OK 74435

County: Sequoyah Year Built: 1969

GPS Coordinates: \_\_\_\_\_ Drive Time: 1 hr

---

**Directions:** From Cherokee Nation,  
Take Hwy-82 South to Indian Rd. [ Keys ]  
Take Indian Rd. south to Hwy 10 Harps Store  
Take Hwy 10 south to Hwy 10 A [ Gore ]  
At Harps Store go west - 4<sup>th</sup> house on left

---

David Tackett

4-8-22

---

Cost Estimator/Inspector

Date



Revised: 1/2017

11/19/2018  
35.5371 N 95.1183 W